

15.0 BUILDING 5653: MAYO AIRPORT TERMINAL BUILDING

15.1 Description of Existing Water Supply System

The Mayo Airport Terminal Building (Building 5653) is currently serviced by a water supply system that delivers water from a 38 m deep well located in a pit below grade. At the time of water system assessment there was no cap on the wellhead, however, it is understood that a cap was installed when Aqua Tech completed well cleaning, downhole video camera inspection and redevelopment work on this well in October 2005. A site plan is provided as Figure 5653-A in Appendix A15. The coordinates of the wellhead, as measured by a handheld GPS device, were recorded as:

- UTM ZONE 8
- Northing: 7054513
- Easting: 456406

This system is equipped with a 5-micron filter however; there is no other treatment or disinfection for this system. A schematic detailing the water system is provided as Figure 5653-B in Appendix A15. Photos of the well and water system are also included at the back of this appendix.

15.2 Description of Existing Wastewater Systems

Wastewater from the terminal building is discharged into a septic system located to the southeast of the building. The tank is approximately 34 m southeast of the well. It is unknown whether the septic system uses a holding tank and sewage education, or an effluent disposal field, however due to the location of the tank it can likely be inferred that a septic field (if present) would be located greater than the required 30 m from the well. A site plan showing the location of the septic tank is given by Figure 5653-A in Appendix A15.

15.3 Water Quality Results

15.3.1 Water Quality Results from Previous Sampling

Bacteriological

Nine samples were collected from the Mayo Airport Terminal Building water system between October 2004 and June 2005 and were tested for total coliform and *E. Coli* by Yukon Environmental Health Services using the presence/absence test method. Results are tabulated in Table 5653-1 in Appendix A15. One sample out of nine reported the presence of total coliform bacteria. The most recent sample results provided, however, reported that coliform bacteria were not present. *E. coli* was reported as not present in all samples for which results were provided.

Potability

YTG representatives collected water samples from the Mayo Airport Terminal Building water system on September 27, 2004. The samples were submitted to Northwest Labs in Surrey BC for potability analyses. Results are summarized in Table 5653-2 in Appendix A15. EBA reviewed the analytical results to compare them with the Canadian Drinking Water Quality Guidelines (CDWQG) to observe general water quality; to identify and recommend additional sampling and analytical; and to identify potential indicators of contamination. Relevant details are as follows:

- At 0.0756 mg/L, the arsenic concentration was above the CDWQG MAC of 0.025 mg/L;
- At 23.5 NTU, turbidity was above both the CDWQG MAC of 1.0 NTU and aesthetic objective (AO) of 5.0 NTU;
- At 2.62 mg/L, the total iron concentration was in exceedence of the CDWQG AO of 0.3 mg/L;
- At 0.272 mg/L, the total manganese concentration was in exceedence of the CDWQG AO of 0.05 mg/L;
- The colour was greater than 60 CU, which is above the CDWQG AO of 15 CU;
- The water quality results indicated that all other health based and AOs were met for the parameters analyzed; and,
- The hardness (as CaCO₃) was 349 mg/L, and is considered very hard.

15.3.2 Identification of Additional Analytical Testing Required

Additional analytical for the Mayo Airport Terminal building that was identified to be included during the water system assessment is detailed below:

- UV absorbance and UV transmissivity, as well as tannins and lignin, to determine potential for UV treatment as a disinfection option for this water system;
- Detailed potability analyses including metals, anions and nutrients;
- Silica and phosphate, to determine the potential for a point of entry arsenic removal system;
- Total organic carbon (TOC); and
- Measurements in the field for total dissolved solids, conductivity, pH, and temperature.

Additional Analytical Results

EBA collected a water sample during the field program on August 17 2005, and shipped it under chain of custody to ALS Environmental in Vancouver BC for analysis of selected parameters as indicated above. The results are summarized in Table 3440-2 in Appendix A15 and the laboratory reports are included in Appendix B. The following points regarding the water quality results are of significance:

- At 65.4 NTU, the turbidity of the water exceeded the CDWQG health based MAC of 5.0 NTU;
- Total arsenic at 0.0575 mg/L was above the CDWQG MAC of 0.025 mg/L, dissolved arsenic at 0.0200 mg/L was below the current MAC, but above the proposed MAC of 0.005 mg/L;
- Total iron at 3.77 mg/L was in exceedence of the CDWQG AO of 0.3 mg/L, dissolved iron concentration was below the laboratory detection limit of 0.03 mg/L indicating that elevated iron is most likely related to elevated turbidity; and
- Total and dissolved manganese at 0.289 and 0.273 mg/L respectively were both above the CDWQG AO of 0.05 mg/L.

15.3.3 Indicators of Potential Contamination

Chloride, nitrate and nitrite concentrations can indicate impacts from surface water sources or septic waste. Chloride concentrations were low and are within the normal background ranges for groundwater in the area. Nitrate and nitrite concentrations for this sample were also low and within the normal background range for this area. These water quality results indicate that the groundwater sample obtained from W-5653 was not under the influence of anthropogenic sources of nutrients or anions that may be derived from septic wastes.

15.4 Conceptual Hydrogeology

A driller's well log was not available for review for this well. Examination of well logs in the Mayo area show that well completion depths and lithology in the area is highly variable. Wells are completed at various depths, ranging from shallow dug wells to drilled wells greater than 150 m deep. The Mayo area has been affected by one or more glaciations, sediments in the Village of Mayo area tend to consist of recent alluvium overlying fine-grained silts with varying interbedded sand and gravel. Sediment deposits are generally underlain by metamorphic bedrock, which is exposed in much of the upland areas. Widespread discontinuous permafrost is known to exist in the Mayo area and has been noted in several of the well logs examined.

The Airport well is completed at a depth of approximately 56 m below grade with a static water level of 7.70 m below ground. Based on topography and proximity to surface water sources, the groundwater flow direction is inferred to be in the range of south to west towards the Mayo and/or Stewart River. Given the depth of the well, and based on the surficial geology of the area, it is likely that the well is completed in a confined aquifer and may have thick sequences of fine grained soils overlying the aquifer.

15.5 Potential Contaminant Sources

Details and photographs of potential contaminant sources observed during the site investigation are compiled in Appendix A15.

Potential contaminant sources within 30 m of the wellhead are:

- An underground fuel storage tank (UST) at 18 m.

In addition, there is a cemetery located 63 m south of the well; the proposed required setback distance from wells to Cemeteries in the proposed Part III - Small Water Systems Regulations is 120 m. As mentioned in the previous section, the well is completed at a depth of 56 m, likely within a confined aquifer and may have thick sequences of fine grained soils overlying the aquifer. Additionally, the well is inferred to be upgradient of the cemetery and the proximity to the cemetery is not considered to be a significant concern.

15.5.1 Spills Records and Contaminated Sites Search Results

It was reported by Environment Canada that three spills occurred in the 1970's at the White Pass and Yukon Route tank farm (WPYR) which is approximately 200 m south of the site. The first spill resulted in approximately 1600 L of furnace oil being discharged due to a mechanical failure. Reportedly the spill was contained and hydrocarbon impacted soils were disposed of off-site. Later in the decade, two other spills resulted in discharges of 3700 L of fuel oil and 1600 L of gasoline respectively. Spill records are included in Appendix A15.

Another spill was reported in 1991 at the WPYR site when an unknown quantity of fuel caught fire and a truck exploded. 756, 000 L of water was used and reportedly, runoff was contained.

Two reported spills also occurred at the North 60 Petroleum Tank Farm in 1997 and 1999 due to the overfilling of a storage tank. Approximately 1000 L of diesel was spilled, however no record of remediation was reported.

The Government of Yukon Environmental Programs Branch and Environment Canada Environmental Protection Branch did not identify any other recorded spill events or contaminated sites issues for this site or neighbouring sites in close proximity.

The well serving this facility is approximately 200 m from the spill site locations in a direction inferred to upgradient. The depth of the well and the fact that it is likely upgradient would provide protection from surficial sources of contamination. It is considered very unlikely that these reported spills or other activities at the bulk fuel sites would have impacted on deep groundwater in the vicinity of the airport well.

15.6 Identified Water System Deficiencies and Associated Risk

15.6.1 High and Medium Risk Deficiencies

High and medium risk deficiencies for this water system that were identified during this study include:

- Poor surface completion of the wellhead (located in a pit below grade);
- There is no surface sanitary seal (grout or bentonite seal as required by the Canadian Groundwater Association's Guidelines for Water Well Construction);
- There is no driller's log available to review well construction and lithology;
- By definition of the Draft Yukon GUDI Assessment Guideline, the well is potentially under the direct influence of surface water because it does not meet the requirements of the Guidelines for Water Well Construction).
- The well is located within 30 m of potential contaminant sources including a UST;
- A water sample collected for bacteriological analysis tested positive for total coliform bacteria;
- The total arsenic concentration was in exceedence of the CDWQG MAC;
- The turbidity was in exceedence of both the CDWQG MAC and AO; and,
- There is no disinfection system present.

We understand that Aqua Tech Services and Supplies Ltd. completed chemical and physical well cleaning and redevelopment in October 2005. It is recommended that a follow-up sample be collected to determine whether well rehabilitation has improved water quality at this well. It is possible that reduced turbidity due to redevelopment will result in lowered iron, manganese and possibly arsenic concentrations. Existing water chemistry will be critical for final treatment system design.

15.6.2 Low Risk Deficiencies

- The Airport's well is located approximately 63 m from the closest property line of the adjacent cemetery, which is less than the proposed 120 m minimum setback distance required within the proposed Part III –Small Water System Regulations. However, based on the inferred groundwater flow direction and depth to well, this is considered a low risk to the drinking water supply serving the Airport;
- The iron concentration was in exceedence of the CDWQG aesthetic objective (AO);
- The manganese concentration was in exceedence of the CDWQG aesthetic objective; and,
- The colour has been reported above the CDWQG AO.

15.7 Mitigative Options for Deficiencies

Without treatment to remove arsenic to below the existing MAC, this water system should not be used for a potable water supply. Advisories and a bottled water station were present on the CARS side of the Terminal at the time of the assessment, however, there were no advisories in the waiting area. Until Priority 1 upgrades are completed, appropriate advisories should be posted on both sides of the airport building.

Mitigative options were developed to address the deficiencies identified in the previous section. Deficiencies are categorized by recommended level of priority (with Priority 1 being most critical).

15.7.1 Priority 1

The following mitigative options should be carried out to address the high-risk deficiencies associated with the water system at the Mayo Airport Terminal Building:

- Standard wellhead upgrades consisting of a pitless unit installation, extension of casing to at least 500 mm above grade, and retrofitting the wellhead with a bentonite/grout surface sanitary seal should be completed.
- A duplex water softener should be installed for UV system pre-treatment and general water quality improvement.

- A NSF/ANSI 55 certified UV system (or equivalent) should be installed to ensure disinfection. These are conceptual design recommendations based on the information available for planning and budgeting purposes. Engineering input will be required for final system specifications.
- A reverse osmosis system should be installed to provide drinking water with arsenic concentrations below the MAC and proposed MAC. The RO would also provide secondary treatment at the dedicated taps because viruses, bacteria and protozoa would not pass through the RO membrane. Dedicated drinking water taps could be plumbed into both sides of the building to provide drinking water to staff and to general public. Signs should be posted indicating that drinking water should be obtained from the dedicated drinking water taps only.
- The well and water system should be shock chlorinated.

15.7.2 Priority 2

The existing UST should be removed and replaced with a double walled tank with “Kamlock” fill connections and flex hosing. Any hydrocarbon-impacted soils should be documented and removed from the site for treatment at a land farm. This work should be completed under the supervision of a qualified environmental consultant.

All other health risks would be mitigated by the proposed Priority 1 upgrades.

15.7.3 Priority 3

The proposed Priority 1 and 2 upgrades should mitigate all health risks associated with this water system. As well, the proposed Priority 1 upgrades should improve aesthetic water quality by reducing hardness, iron and manganese, which would help to reduce fixture staining and plumbing encrustation. The wellhead upgrades, UV treatment and RO system installation in Priority 1 would further reduce any risk to water quality posed by the existing cemetery that is 63 m south of the well.

15.8 Cost Estimates for Mitigative Options

Engineering costs for mitigative options are estimated to be 20% of construction costs, and would include inspection and completion reporting. The costs for materials and labour (not including engineering) are provided in the sections below. An additional contingency allowance of 20% is suggested for budgetary purposes.

15.8.1 Priority 1

Class D cost estimates for mitigative options to address the high-risk deficiencies for this site are as follows:

- To complete the recommended wellhead upgrades consisting of pitless unit installation, well casing extension, piping and heat trace upgrades would cost in the order of **\$5,000** for materials and labour.
- A filtration and UV treatment/disinfection system would likely amount to a total installed cost of about **\$3,000**;
- A duplex softening system of adequate size would cost approximately **\$4,000** installed; and,
- Supply and installation of a reverse osmosis system with a dedicated drinking water tap in the kitchen areas and in the terminal waiting area would cost approximately **\$800**.



Therefore the total estimated cost for all recommended Priority 1 upgrades is approximately **\$12,800**.

15.8.2 Priority 2

Estimated costs for UST removal, tank disposal, removal of any associated hydrocarbon impacted soils, and replacement with a double walled AST with Kamlock fill connection and flex hose would cost in the order of **\$8,000** assuming that there is negligible soil contamination. The costs could be significantly higher if soil contamination is present in the vicinity of the building.

15.8.3 Priority 3

There are no recommended Priority 3 upgrades at this time. Priority 1 and 2 upgrades should mitigate all health risks.



WELL 5653
 N 7 054 513
 E 456 406
 DRILLERS REPORT
 NO.: n/a

Grassy Field

Fence

Airport Apron

MAYO AIRPORT
 TERMINAL
 BUILDING
 BLDG. #5653

Gravel Parking

UST Heating Oil
 Fill & Vent

Standby Diesel
 Generator

Septic Tank


Electrial Supplies

Likely Location
 of Septic Field


Fence

NOT EXACTLY
 AS SHOWN


NOTES:
 1. UTM COORDINATES OBTAINED WITH A HAND HELD GPS USING NAD83 SYSTEM AND ARE CONSIDERED TO BE ACCURATE TO 10.0 m, APPROXIMATELY.

 30 m RADIUS FROM WATER WELL FOR CONSIDERATION OF PROXIMITY TO POTENTIAL CONTAMINANT SOURCES.

| No. | DESCRIPTION | DATE | APPROVED |
|----------|--------------------------|----------|----------|
| 0 | ISSUED FOR CLIENT REVIEW | DD/MM/YY | XXX |
| REVISION | | | |

 **EBA Engineering Consultants Ltd.**

DESIGNED BY: R. MARTIN
 DRAWN BY: J. BUYCK
 DATE: SEPT. 2005
 SCALE: AS SHOWN
 PROJECT No.: 1260002.004
 ACAD FILENAME: 004-NORTHERN REGION

CLIENT:

 Highways and Public Works
 Property Management Branch

SMALL PUBLIC WATER SYSTEMS ASSESSMENT
 NORTHERN REGION


GOVERNMENT OF YUKON
 HIGHWAYS & PUBLIC WORKS



MAYO TERMINAL BUILDING
 BUILDING # 5653
 SITE LOCATION DIAGRAM
 WELL ID: 5653


REVISION ISSUE
 0

FIGURE No.
 FIGURE 5653-A



LEGEND



| | | | | |
|--|---|-----------|------------------|--------------|
|  EBA Engineering Consultants Ltd. | PROJECT SMALL PUBLIC WATER SYSTEMS ASSESSMENT WESTERN REGION | | | |
| CLIENT <div style="text-align: center;">  Highways and Public Works Property Management Branch </div> | TITLE <h3 style="text-align: center;">SCHEMATIC SYSTEM LEGEND</h3> | | | |
| DATE APRIL 2006 | DWN. JSB | CHKD. RMM | FILE NO. 1260002 | DRWG. LEGEND |



DRAWING IS BASED UPON SCHEMATIC PROVIDED BY BERT ALBISSER OF AQUA TECH SUPPLIES AND SERVICES LTD.

| | | | | | | | | | |
|---|------------|---|-----|-------|-----|----------|-------------|-------|---------------|
|  EBA Engineering Consultants Ltd. | | PROJECT SMALL PUBLIC WATER SYSTEMS ASSESSMENT NORTHERN REGION | | | | | | | |
| CLIENT  | | TITLE WATER SYSTEM DISTRIBUTION/TREATMENT SCHEMATIC SYSTEM ID.: 5653 AIR TERMINAL BUILDING - MAYO, YT. | | | | | | | |
| DATE | SEPT. 2005 | DWN. | JSB | CHKD. | RMM | FILE NO. | 1260002.004 | DWG.: | FIGURE 5653-B |

**Northern Region – Airport Terminal Building
Building # 5653**

DISTRIBUTION & TREATMENT SYSTEM DATA

| Item | Description | Manufacturer | Model | Part No. | Serial No. | Size |
|------|-----------------|--------------|----------|----------------------|------------|----------------|
| 1 | SUB PUMP | MONARCH | SBS EX | | | 3/4HP - 4" |
| 2 | PRESSURE TANK | CHALLENGER | PC66 | | | 20 GALLON |
| 3 | PRESSURE SWITCH | SQUARE D | FSG-2 | | | 2HP - 1/4" FPT |
| 4 | PRESSURE GAUGE | MARSH | 0-100-2" | | | 2" - 1/4" FPT |
| 5 | INLINE FILTER | ENVIRO GUARD | 5 MICRON | SEP & 30 MILLION GAC | | 10" - 3/4" |
| 6 | | | | | | |
| 7 | | | | | | |
| 8 | | | | | | |
| 9 | | | | | | |
| 10 | | | | | | |

TABLE 5653- 1: SUMMARY OF BACTERIOLOGICAL RESULTS

| | | Number of Sampling Events | Time Period over which Sampling was Done | Any Positive Total Coliform Results? (yes or no) | Fraction of Positive Total Coliform Results vs. Total Sampling Events | Any positive E.Coli results? (yes or no) | Most Recent Sampling Event Available for EBA Review | Is Most Recent Result Positive? |
|------------|--------------------------------|---------------------------|--|--|---|--|---|---------------------------------|
| Building # | Building Name | | | | | | | |
| 5653 | Mayo Airport Terminal Building | 9 | Oct-04 to Jun-05 | yes | 1/9 | no | 9-Jun-05 | no |



Table 5653 - 2: Water Quality Results

| SOURCE: | | Building 5653 - Mayo Airport Terminal Building | | GCDWQ Criteria | | |
|-------------------------------|--|--|------------------------|---|-------------|------|
| Location/ Resident | | Mayo | | | | |
| Address | | | | | | |
| Treatment | | Filtration | | | | |
| Disinfection | | None | | | | |
| Source of Water | | On-site well | | | | |
| Purpose of Sampling | | Base Line | Additional Sampling | | | |
| Sample Location | | | Washroom faucet | | | |
| Date Sampled | | 27-Sep-04 | 17-Aug-05 | Lower | Upper Limit | |
| Physical Tests (ALS) | | | | AO | MAC | AO |
| Colour (CU) | | >60 | <5.0 | | | 15 |
| Conductivity (uS/cm) | | 388 | 652 | | | |
| Total Dissolved Solids | | 388 | 436 | | | 500 |
| Hardness CaCO3 | | 349 | 333 | AO >200 = poor, > 500 unacceptable ^A | | |
| pH | | 8.14 | 8.15 | 6.5 | | 8.5 |
| Turbidity (NTU) | | 23.5 | 65.4 | | 1 | 5 |
| UV Absorbance | | | 0.027 | | | |
| % UV Transmittance | | | 94 | | | |
| Dissolved Anions (ALS) | | | | | | |
| Alkalinity-Total CaCO3 | | 313 | 296 | | | |
| Chloride Cl | | <0.5 | <0.50 | | | 250 |
| Fluoride F | | 0.11 | 0.121 | | 1.5 | |
| Silicate SiO4 | | | 11.4 | | | |
| Sulphate SO4 | | 72.8 | 85.8 | | | 500 |
| Nitrate Nitrogen N | | <0.01 | <0.10 | | 10 | |
| Nitrite Nitrogen N | | <0.005 | <0.10 | | 1 | |
| Ammonia Nitrogen N | | | | | | |
| Total Phosphate PO4 | | | 0.0794 | | | |
| Total Metals (ALS) | | | | | | |
| Aluminum T-Al | | <0.005 | <0.010 | | 0.1 | |
| Antimony T-Sb | | <0.0002 | <0.00050 | | 0.006 | |
| Arsenic T-As | | 0.0756 | 0.0575 | | 0.025 | |
| Barium T-Ba | | 0.037 | 0.033 | | 1 | |
| Boron T-B | | 0.011 | <0.10 | | 5 | |
| Cadmium T-Cd | | <0.00001 | <0.00020 | | 0.005 | |
| Calcium T-Ca | | | 83 | | | |
| Chromium T-Cr | | 0.0019 | <0.0020 | | 0.05 | |
| Copper T-Cu | | <0.001 | <0.0010 | | 1 | |
| Iron T-Fe | | 2.62 | 3.77 | | | 0.3 |
| Lead T-Pb | | <0.0001 | <0.0010 | | 0.01 | |
| Magnesium T-Mg | | | 30.7 | | | |
| Manganese T-Mn | | 0.272 | 0.289 | | | 0.05 |
| Mercury T-Hg | | | <0.00020 | | 0.001 | |
| Potassium T-K | | | 2.04 | | | |
| Selenium T-Se | | | <0.0010 | | 0.01 | |
| Sodium T-Na | | 8.7 | 9.6 | | | 200 |
| Uranium T-U | | <0.0005 | 0.00042 | | 0.02 | |
| Vanadium T-V | | | <0.030 | | | |
| Zinc T-Zn | | 0.026 | 0.196 | | | 5 |
| Dissolved Metals | | | | | | |
| Arsenic D-As | | | 0.0200 | | 0.025 | |
| Iron D-Fe | | | <0.030 | | | 0.3 |
| Manganese D-Mn | | | 0.273 | | | 0.05 |
| Organic Parameters | | | | | | |
| Tannin and Lignin | | | 0.41 | | | |
| Total Organic Carbon C | | | 2.17 | | | |
| Field Chemistry (EBA) | | | | | | |
| pH | | | 8.13 | 6.5 | | 8.5 |
| TDS (ppm) | | | 324 | | | 500 |
| EC (uS/cm) | | | 649 | | | |
| Temperature (°C) | | | 5.6 | | | |
| Free Available Chlorine | | | | | | |

Notes:

A. Guidelines indicated for hardness are not CDWQG, rather they are general aesthetic guidelines
 - exceedences are indicated in yellow highlighting.

Italics and underline indicates exceedence of proposed MAC (ie. arsenic)

Bold with Yellow highlighting indicates exceedence of CDWQG Aesthetic Objective (AO)

Bold Underline with Yellow highlighting indicates exceedence of CDWQG MAC

Results are expressed as milligrams per litre except for pH and Colour (CU)

Conductivity (umhos/cm), Temperature (°C) and Turbidity (NTU)

< = Less than the detection limit indicated.

AO = Aesthetic Objective

MAC = Maximum Acceptable Concentration (Health Based)



EBA Engineering Consultants Ltd.

Creating and Delivering Better Solutions

SMALL PUBLIC WATER SYSTEM ASSESSMENT

PART A: EBA Site Inspection

Inspector: Ryan Martin, Luke Lebel

Date August 17, 2005

| WELL ID # | Owner | Location Description |
|-----------|-------|--------------------------------|
| 5653 | YTG | Mayo Airport Terminal Building |

1. Well Location and Potential Contaminant Sources

a. General location of well: (Community, Subdivision, etc.)

Mayo

b. Specific location: (Road or street, Building number, name of owner and/, legal description,

Mayo Airport

c. GPS location: N 7054513 E 456406 elev 508m ± 12m

d. Is there electric power? Yes No

e. Is there outside water access? Yes No

f. Does the well system have:

15 or more service connections to a piped distribution system? If so how many _____

Mayo Airport Terminal Building

5 or more delivery sites on a trucked distribution system? If so how many _____

g. Nearest building, specify Terminal building

h. Distance from well to building ~ 3m

i. If there is an effluent disposal field, is its location known? Yes No

j. Distance from well to nearest point of known field: Tank @ ~34m, field >34m (if present)

k. Well location relative to field: upslope downslope lateral

EBA Engineering Consultants Ltd.

Creating and Delivering Better Solutions

l. Is there any part of a sewage disposal system(s) or other potential sources of pollution that may pose a health and safety risk within 30 m? Yes No

Service lines only. Septic tank is pumped once per year. There may be a field, but unknown

m. Is the well located within 300 m from a sewage lagoon or pit? Yes No unlikely

n. Is the well located within 120 m from a solid waste site or dump, cemetery? Yes No
~63m from cemetery

o. Is the infrastructure protecting the wellhead, pumphouse, storage tank and/or water treatment plant designed and secured to prevent:

Unauthorized access by humans? Yes No
Unlocked enclosure

Entrance by animals? Yes No
Access possible

p. Is well site subject to flooding? Yes No

q. Is the well site well drained? Yes No

r. Is there a buried fuel tank on the property? Yes No

If yes, is it in use abandoned

Is the location known? Yes No

Distance from the well to known buried tank ~18 m

s. Are there any other known contaminant sources on the property?

Yes No Describe _____

If yes, specify the source: dump sewage lagoon cemetery other

Potential Source 1: Bulk fuel storage; Distance from well to Potential Source 1: >60m

Potential Source 2: _____; Distance from well to Potential Source 2: _____

Potential Source 3: _____; Distance from well to Potential Source 3: _____

Potential Source 4: _____; Distance from well to Potential Source 4: _____

t. Are there other wells on this property? Yes No unlikely

How many? _____ in use abandoned require proper sealing

EBA Engineering Consultants Ltd.

Creating and Delivering Better Solutions

2. Well and Wellhead information:

- a. When was well installed? Year unknown Month _____
- b. Type: drilled dug sand point other _____
- c. Is there a drillers log for the well: Yes No
- d. Is there a surface seal to 6 m Yes No unknown unlikely
- e. Surface casing: Yes Diameter _____ No
- f. Well casing: Diameter 15 cm Material: steel plastic concrete
- g. Depth of well: 38.100 m bc ^{could be pump} measured (if possible) reported from log
- h. Static water level below ground: 7.700 m bc
 measured (if possible) reported from log flowing
- i. (If granular) Is the well completed: open end casing with a well screen
 with slotted pipe unknown other _____
- j. (If bedrock) Does the well have a liner? yes No steel plastic
- k. If there is a well screen: length _____ slot size(s) _____
Location of screen: from _____ to _____ from log reported
- l. Is there a sump below the screen? Yes No unknown
- m. Is the well head: in pumphouse in pit pitless adaptor in a building
 in a wooden enclosure other, describe _____
- n. If the well head is located in a wooden enclosure,

EBA Engineering Consultants Ltd.

Creating and Delivering Better Solutions

- i. Is the well head below grade? describe in detail ~ 1.2m bg
- ii. Are there signs of ponding on the enclosure(e.g. water stains, etc.)? Yes No
- iii. Is the wellhead enclosed by fiberglass insulations? Yes No has been removed
- iv. Any evidence of rodents? Specify Access possible
- v. Does the well casing have a proper seal cap? Yes No

If no, describe condition No cap - only garbage bag above well casing

3. Water Supplying This Well:

- a. By definition is the water from a surface water source or under the direct influence of surface water?
 Yes No farther investigation required.

If yes is there treatment or disinfection Yes No

Explain (filtration, disinfection etc...) _____

4. Aquifer Supplying This Well:

- a. The aquifer is: bedrock granular sediment unknown

- b. Does water level and/or well capacity show seasonal fluctuation? Yes No
unlikely

5. Pump Installation:

- a. Is the well equipped with a pump? yes No

- b. Type of pump: hand electric submersible jet

shallow well centrifugal other, _____

- c. Description: Manufacturer _____ Model _____
horsepower _____ capacity _____ voltage _____

EBA Engineering Consultants Ltd.

Creating and Delivering Better Solutions

d. Date installed: _____ By: _____

e. For submersible pump, depth of setting below surface _____

f. Drop pipe for submersible pump: steel plastic

g. Pump delivers water to: pressure tank elevated tank other

h. Are there automatic pump controls: Yes No

i. Is there provision for taking water samples before water reaches storage? Yes No
But directly against floor

j. Is there a water meter on the system? Yes No

k. Is the pump and piping protected from freezing? Yes No

If yes, describe: Has been disconnected/removed

l. Comments on pump installation: _____

6. Conclusions

a. Comments on overall installation:

b. Recommendations: _____

EBA Engineering Consultants Ltd.

Creating and Delivering Better Solutions

PART B: EBA Site Inspection

Inspector: BERT ALBISSER

Date AUG 17 / 05

| WELL ID # | Owner | Location Description |
|-------------|------------|----------------------|
| <u>5653</u> | <u>YTG</u> | <u>MAYO AIR PORT</u> |

6. Water Treatment

a. Is well water treated? Yes No; Type of treatment:

chlorination iron and or manganese removal other _____

b. Is water entering plumbing or piped distribution system treated with chlorine or another treatment that is as effective as chlorine used to achieve disinfection throughout the system?

Yes No If so how _____

c. If treated with chlorine, is the free residual chlorine concentration less than 0.2 mg/L

Yes No _____ reading.

Tested at _____ (location)

d. Is testing for chlorine residual concentration done at the tap (eg. Kitchen faucet) or from representative points in a piped distribution system, including a point from tap at the end line

Yes No If yes how often? _____

e. If the drinking water is being transported by water delivery truck does it have a minimum chlorine free residual of 0.4 mg/L at the time of fill. Yes No

7. Water Quality (observations):

a. Does the water stain plumbing? yes No slight severe

Type of stain: brown red black

b. Does the water contain sediment? Yes No occasional constant

c. Is there an unpleasant odour? Yes No H₂S Other _____

EBA Engineering Consultants Ltd.

Creating and Delivering Better Solutions

- d. Is there an unpleasant taste? Yes No brackish Other _____
- e. Is there a history of bad bacterial analyses? Yes No ?
- f. Is there a chemical analysis? Yes No adequate incomplete
- g. Is there analysis of trihalomethanes (THMs) where the water source is a surface water supply or a well under the direct influence of surface water? Yes No
- h. Is the drinking water tested daily with an accurate reading chlorine test kit capable of reading in the range 0 to 3.5 mg/L of free chlorine residual in increments of 0.1mg/L? Yes No unknown
- i. If yes is the test performed in accordance with manufactures directions? Yes No unknown
- j. Is a record of the date, time, name of person performing the test and results of the drinking water sample kept? Yes No

TANK AND PIPING DETAILS

Tank Room

Is there a water tank? Yes No Details: PRESSURE TANK

Where is it located?

Comments: FURNACE ROOM

Is the room in which the water tank is located heated to maintain an optimum temperature of 4°C for stored water?

YES NO

Comments: _____

Are there windows in the add-on that may allow direct sunlight onto the water holding tank? YES

NO

Comments: _____

Are there other heat sources near the tank? YES NO

Comments: _____

Is there waterproof flooring with a sealed base to contain spills? YES NO

Comments: _____

Overall Tank

What are the tank size and dimensions?

What material is the tank constructed of? _____

Is tank and associated piping constructed of safe materials (i.e. CSA approved and material that does not affect the taste of the water)? YES NO

Comments: _____

Tank Inlet, Outlet and Lid

Is there adequate access on the tank for cleaning (i.e. min 15" access lid)? YES NO

Does the lid have a tight seal and is it watertight when closed? YES NO

Does the tank have an overflow or high level whistle? YES NO

Is the water tank drain accessible? YES NO

WATER TANK AND WATER QUALITY CONDITION

Are there signs of staining or biofouling? YES NO

Comments: _____

Is there any sediment or scum in bottom of tank? YES NO

Comments: _____

Is there any odour associated with the water or tank? YES NO

Have there been any bacteriological analyses conducted previously? YES NO

Does the tank appear that it has been cleaned recently? YES NO

Are the tanks easily assessed for the purpose of cleaning and disinfection? YES NO

8. Conclusions

a. Comments on overall installation:

THE WATER SYSTEM IS OLD AND JUDGING BY
SCUM AND RUST-BUILDUP IN JANITORIAL SINK IN
FURNACE ROOM, HEAVILY SCALED UP WITH CALCIUM
& RUST DEPOSIT.

b. Recommendations:

INSTALL COMMERCIAL TREATMENT SYSTEM AS
DICTATED BY THE CHEMICAL ANALYSIS
PAST KNOWLEDGE I WOULD RECOMMEND
DUPLEX SOFTNER SYSTEM, SMALL COMMERCIAL
RO SYSTEM WITH LARGE PRESSURE TANK.



Spill Report Information

| | |
|----------------------------|---|
| Spill # | 7613 |
| Jurisdiction | Yukon |
| Community | Mayo |
| Address | |
| Highway | |
| Milepost | |
| Feature | Mayo |
| Location and Cause | WPYR tank farm - failure of loading hose |
| Latitude | 63.6133333333333 |
| Longitude | -135.879166666667 |
| Incident Date | 8/26/1976 10:00:00 PM |
| Lead Agency | Department of Indian Affairs and Northern Development |
| Other Agency | |
| Company(s) | White Pass & Yukon Route |
| Amount | 1512 |
| Units | Litres |
| Quantity | Actual |
| Release Description | Spilled |
| Additional Quantit | |
| Concentration | |
| Concentration Unit | |
| Phase | Liquid |
| Major Contaminant | Furnace Oil |
| 2nd Contaminant | |
| 3rd Contaminant | |
| 4th Contaminant | |
| Outcome | spill dyked off immediately - contaminated area 15' x 150' - cleaned-up (contaminants removed to Mayo dump) |



Spill Report Information

| | |
|-----------------------------|---|
| Spill # | 7718 |
| Jurisdiction | Yukon |
| Community | Mayo |
| Address | |
| Highway | |
| Milepost | |
| Feature | Mayo |
| Location and Cause | tank farm - tank overfilled |
| Latitude | 63.6133333333333 |
| Longitude | -135.879166666667 |
| Incident Date | 8/22/1977 9:00:00 AM |
| Lead Agency | Environment Canada - Environmental Protection Service |
| Other Agency | Department of Indian Affairs and Northern Development |
| Company(s) | White Pass & Yukon Route |
| Amount | 3742 |
| Units | Litres |
| Quantity | Actual |
| Release Description | Spilled |
| Additional Quantitit | |
| Concentration | |
| Concentration Unit | |
| Phase | Liquid |
| Major Contaminant | Fuel Oil |
| 2nd Contaminant | |
| 3rd Contaminant | |
| 4th Contaminant | |
| Outcome | no fuel recovered - possible contamination of groundwaters but not known - suggests action be taken as too many spills with no recovery in area |



Spill Report Information

| | |
|-----------------------------|---|
| Spill # | 7727 |
| Jurisdiction | Yukon |
| Community | Mayo |
| Address | |
| Highway | |
| Milepost | |
| Feature | Mayo |
| Location and Cause | tank farm - tank overfilled |
| Latitude | 63.6133333333333 |
| Longitude | -135.879166666667 |
| Incident Date | 3/28/1977 9:00:00 AM |
| Lead Agency | Environment Canada - Environmental Protection Service |
| Other Agency | |
| Company(s) | White Pass & Yukon Route |
| Amount | 1512 |
| Units | Litres |
| Quantity | Actual |
| Release Description | Spilled |
| Additional Quantitit | |
| Concentration | |
| Concentration Unit | |
| Phase | Liquid |
| Major Contaminant | Gasoline |
| 2nd Contaminant | |
| 3rd Contaminant | |
| 4th Contaminant | |
| Outcome | spill within dyke - none reported outside dyke - cleaned-up |



Spill Report Information

| | |
|----------------------------|--|
| Spill # | 9130 |
| Jurisdiction | Yukon |
| Community | Mayo |
| Address | |
| Highway | |
| Milepost | |
| Feature | Mayo |
| Location and Cause | White Pass yard - garage caught on fire - explosion ensued |
| Latitude | 63.6166666666667 |
| Longitude | -135.884444444444 |
| Incident Date | 11/26/1991 |
| Lead Agency | Yukon Government - Fire Marshall |
| Other Agency | |
| Company(s) | White Pass |
| Amount | |
| Units | |
| Quantity | Unknown |
| Release Description | Burned |
| Additional Quantit | |
| Concentration | |
| Concentration Unit | |
| Phase | Liquid |
| Major Contaminant | Hydrocarbons |
| 2nd Contaminant | |
| 3rd Contaminant | |
| 4th Contaminant | |
| Outcome | fuel or propane truck exploded inside building - building consumed - used 756,000L water - water runoff contained in ditch - oil and fuel in water |



Spill Report Information

| | |
|-----------------------------|--|
| Spill # | 9703 |
| Jurisdiction | Yukon |
| Community | Mayo |
| Address | |
| Highway | |
| Milepost | |
| Feature | Mayo |
| Location and Cause | North 60 Petroleum Bulk Plant - overfill of bulk storage tank - miscommunication between truck operator and plant operator |
| Latitude | 63.6134 |
| Longitude | -135.8793 |
| Incident Date | 1/15/1997 6:40:00 PM |
| Lead Agency | Yukon Government - Public Safety |
| Other Agency | Environment Canada - Environmental Protection Service |
| Company(s) | North 60 Petroleum |
| Amount | 1000 |
| Units | Litres |
| Quantity | Estimate |
| Release Description | Spilled |
| Additional Quantitit | |
| Concentration | |
| Concentration Unit | |
| Phase | Liquid |
| Major Contaminant | Diesel |
| 2nd Contaminant | |
| 3rd Contaminant | |
| 4th Contaminant | |
| Outcome | 300 L recovered - EC recommended excavation of contaminated soil and installation of monitoring wells - fuel discrepancy of 22,000 L reported by Mayo plant - not verified |



Spill Report Information

| | |
|-----------------------------|--|
| Spill # | 9947 |
| Jurisdiction | Yukon |
| Community | Mayo |
| Address | |
| Highway | |
| Milepost | |
| Feature | Mayo |
| Location and Cause | North 60 Petroleum Tank Farm - overfill of storage tank |
| Latitude | 63.6134 |
| Longitude | -135.8793 |
| Incident Date | 12/10/1999 5:10:00 PM |
| Lead Agency | Environment Canada - Environmental Protection Service |
| Other Agency | |
| Company(s) | North 60 Petroleum |
| Amount | |
| Units | |
| Quantity | Unknown |
| Release Description | Spilled |
| Additional Quantitit | negligible amount |
| Concentration | |
| Concentration Unit | |
| Phase | Liquid |
| Major Contaminant | Diesel |
| 2nd Contaminant | |
| 3rd Contaminant | |
| 4th Contaminant | |
| Outcome | overfill caused product to run down sides of tank and small amount to ground at base of tank within berm - no loss noted in records check - minimal amount spilled - no action |



Photo 0187: 5653 Mayo Airport wellhead enclosure.



Photo 0189: 5653 Pressure tank and pump controls.



Photo 027: 5653 Mayo Airport Terminal Building.



Photo 007: 5653 Septic tank (front) and bulk fuel storage (back).