



LORAX
ENVIRONMENTAL

MW14-06B / BH7 / CFD-0463

(Page 1 of 2)



Drilling Started : Sep 22, 2014
Install Completed : Sep 24, 2014
Drilling Method : Diamond / PQ
Drilling Company : CYR Drilling Ltd.
Supervised By : LF/RW/GB

Northing Coord. : 6,974,583.17
Easting Coord. : 585,195.39
Ground Surface : 1183.3 m amsl
Logged By : Kaminak
Checked By : LF

Coffee Creek Gold
Project #: A362-4

Depth (m)	Elev. (m amsl) 1183.3	DESCRIPTION	RQD (%)		Fracture = Fr Fault = FIt	Packer Test Interval (mbgs)	K (m/s)	Depth (m)
			0	50				
		Water Level: 1053.32 m amsl 07-Oct-14 @ 11:15 (approximate)						Well: MW14-06B Elev.: 1184.3 m amsl (TOC)
0		OVERBURDEN						
1180		GNEISS Weak to moderate fracture controlled and interstitial limonite alteration and clay alteration to feldspars						Surface Casing Collapsed Abandoned in 2015
10		HYDROTHERMALLY ALTERED ROCK Zone						
1170		GNEISS Weak to moderate fracture controlled and interstitial limonite alteration						
20		HYDROTHERMALLY ALTERED ROCK Zone. Bleached and silicified medium grained, monomictic clasts supported in a pale yellow clay 12.8 to 17.5 m						
1160		ANDESITE Zone. Strongly oxidised and limonite altered mafic dyke				N/A	N/A	
30		GNEISS Weak fracture controlled limonite alteration						
1150								
40					Fr			2" Sched. 80 PVC
1140								Cement Grout
50								
1130								
60								
1120								
70								
1110								
80								
1100								
90								




Drilling Started : Sep 22, 2014
 Install Completed : Sep 24, 2014
 Drilling Method : Diamond / PQ
 Drilling Company : CYR Drilling Ltd.
 Supervised By : LF/RW/GB

Northing Coord. : 6,974,583.17
 Easting Coord. : 585,195.39
 Ground Surface : 1183.3 m amsl
 Logged By : Kaminak
 Checked By : LF

Coffee Creek Gold
 Project #: A362-4

Depth (m)	Elev. (m amsl) 1183.3	DESCRIPTION	RQD (%)		Fracture = Fr Fault = FIt	Packer Test Interval (mbgs)	K (m/s)	Depth (m)
			0	50				
		Water Level: 1053.32 m amsl 07-Oct-14 @ 11:15 (approximate)						Well: MW14-06B Elev.: 1184.3 m amsl (TOC)
90								
1090		ANDESITE Sharp fg dark-grey black dykes						
100		GNEISS Felsic bands common augens occ bt schist +/- amph, occ band pervasive pink = hematite? <1m						
1080								
110								
1070								
120								
1060								
130					N/A	N/A		
1050		*Iron stained fractures 133.3 to 136.0 m suggesting presence of water						
140								
1040		HYDROTHERMALLY ALTERED ROCK Minimal zone mix ox & sulph						
150		*Iron stained fractures at ~144 and 148 m suggesting presence of water						
1030		GNEISS Felsic bands common augens occ bt schist +/- amph, occ band perv pink = hematite? <1m						
160								
1020								
		EOH @ 164.4 m						
170		N/A: Borehole not packer tested						
1010								
180								



03-04-2016 P:\A362-4 (Coffee Gold Project - Hydrogeology)\Data\BH Logs\Quicklog\2014\MW14-06B.bor