

001378

URGENT!  AS SOON AS POSSIBLE

02363

FROM J. Mathis

DEPT. SRK

COPY TO L. Hwozdyk

DATE 07/03/90

SUBJECT Bolting.

SEND TO

CMD - JACK RETZA  
- LANCE FLEWELLING

MESSAGE

Recommended that bolts / straps be installed across fault zone ~~to~~ along ribs near face of SQ 300. Material is soft and appears to be shearing - should be supported (Appx 10' on each side of drift)

REPLY

4S500E - 1

← SPEEDIMEMO →

MOORE SPEEDIPLY - 1 - MOORE CLEAN PRINT PATENTED 1963-1966

REPLY FROM

DATE

WRITE REPLY IN BOTTOM AREA  
RETAIN ORIGINAL & RETURN THIS COPY.

