

WELL V-115-R
DEPTH 54
PICTURE NO. 5
INCLINATION 4°
OBS. DIR. N70E
COR. DIR. 103
TOOL FACE
RUN BY DTH
DATE June 26/79
CHECKED BY _____



sperry-sun

SP-132 (11-74)

WELL V-115-R
DEPTH 154
PICTURE NO. 1
INCLINATION 5.5°
OBS. DIR. N50E
COR. DIR. 090°
TOOL FACE
RUN BY DTH
DATE June 26/79
CHECKED BY _____



sperry-sun

SP-132 (11-74)

WELL V-115-R
DEPTH 234
PICTURE NO. 3
INCLINATION 5.75°
OBS. DIR. N63E
COR. DIR. 096°
TOOL FACE
RUN BY DTH
DATE June 26/79
CHECKED BY _____



sperry-sun

SP-132 (11-74)

WELL V-115-R
DEPTH 354
PICTURE NO. 2
INCLINATION 5.5°
OBS. DIR. N78E
COR. DIR. 111°
TOOL FACE
RUN BY DTH
DATE
CHECKED BY _____



sperry-sun





SP-132 (11-74)

WELL V-115-R
DEPTH 454
PICTURE NO. 1
INCLINATION 10°
OBS. DIR. N76E
COR. DIR. 109°
TOOL FACE
RUN BY DTH
DATE June 26/79
CHECKED BY _____



sperry-sun

SP-132 (11-74)



020639