

WELL V 114 R
DEPTH 432
PICTURE NO. 2
INCLINATION 5.5
OBS. DIR. N07W
COR. DIR. 026°
TOOL FACE _____
RUN BY AL
DATE JUNE 13
CHECKED BY _____



sperry-sun

SP-132 (11-74)

WELL V 114 R
DEPTH 432
PICTURE NO. 3
INCLINATION 1.5
OBS. DIR. S42E
COR. DIR. 171
TOOL FACE _____
RUN BY AL
DATE JUNE 13
CHECKED BY _____



sperry-sun

SP-132 (11-74)

WELL V-114 R
DEPTH 342
PICTURE NO. 4
INCLINATION 2.3
OBS. DIR. N68W
COR. DIR. 292°
TOOL FACE _____
RUN BY AL
DATE JUNE 13
CHECKED BY _____



sperry-sun

SP-132 (11-74)

WELL V-114 R
DEPTH 672
PICTURE NO. 1
INCLINATION 10.5
OBS. DIR. _____
COR. DIR. _____
TOOL FACE _____
RUN BY AL
DATE JUNE 13
CHECKED BY _____



sperry-sun

SP-132 (11-74)

WELL V 114 R
DEPTH 128
PICTURE NO. 8
INCLINATION 20
OBS. DIR. N123E
COR. DIR. _____
TOOL FACE _____
RUN BY AL
DATE JUNE 13
CHECKED BY _____



sperry-sun

SP-132 (11-74)

WELL V 114 R
DEPTH 262
PICTURE NO. 5
INCLINATION 1.9
OBS. DIR. N00E
COR. DIR. 033
TOOL FACE _____
RUN BY AL
DATE JUNE 13
CHECKED BY _____



sperry-sun

SP-132 (11-74)

020649