



P.O. Box 4391

FIELD REPORT

Started. Nov. 14...1994
 Completed. Nov. 18...1994

filled ✓

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
<i>Laywire Industrial W/W Harry Kern</i>		<i>Fire Hall Robinson Subdiv.</i>

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE				
			<i>Loading</i>	<i>Nov. 14</i>	<i>8:00</i>	<i>9:00</i>	<i>1</i>
			<i>move on set up</i>	<i>"</i>	<i>9:00</i>	<i>11:30</i>	<i>2.5</i>
<i>0</i>	<i>7</i>	<i>silt</i>		<i>"</i>	<i>11:30</i>	<i>5:00</i>	<i>5.5</i>
<i>7</i>	<i>10</i>	<i>Gr. sand.</i>					
<i>0</i>	<i>22</i>	<i>fine sand</i>					
<i>2</i>	<i>46</i>	<i>fine sand some Gr.</i>					
<i>16</i>	<i>71</i>	<i>Gr. sand</i>					
<i>21</i>	<i>97</i>	<i>Gr. silt sand.</i>					
<i>7</i>	<i>114</i>	<i>Gr. sand some silt</i>					
			<i>crew travel</i>	<i>"</i>	<i>5:00</i>	<i>6:00</i>	<i>1</i>
			<i>crew travel</i>	<i>Nov. 15</i>	<i>8:00</i>	<i>9:00</i>	<i>1</i>
			<i>set screen</i>	<i>"</i>	<i>9:00</i>	<i>10:30</i>	<i>1.5</i>
			<i>Develop</i>	<i>"</i>	<i>10:30</i>	<i>1:00</i>	<i>2.5</i>
			<i>move off to shot</i>	<i>"</i>	<i>1:00</i>	<i>2:30</i>	<i>1.5</i>

Sched. of Casing & Pipe				Remarks:
Size	Type	Size	Type	
<i>6</i>				<i>30-GPM. 1- drive shoe 20 slot screen 2' riser & Packer 5/8" bit pin</i>
feet	Inch	Feet	Inch	
<i>12</i>				

STATIC LEVEL		Total Rig Time	hrs.
Ground level	<i>60'</i>	Total Standby	hrs.
Top of casing		Drilling Mud	sacks

SIGNATURES

MIDNIGHT SUN.....
 TITLE.....

CLIENT.....
 TITLE.....