

Nov. 2-69 000726

TEST DRILLING 4100'

4065

STARTED 8⁰⁰

Hole # 4. - drilled 1st.

0-23. waste.

23-35 very poor

35-58 " "

58- hit ore.

58-75 - ore (lots of pyrite).

COMPLETED - 10³⁵

0-35 - 5395

35-70 - 5396

5397

HOLE # 1 - drilled 2nd.

CHANGED TO BUTTON BIT & REPAIR AIR

STARTED - 1055.

LWII

0-30 - waste.

30-35 - dark cuttings - waste(?)

35-70 - intermittent dark & light
cuttings

COMPLETED 1200.

0-35-5398

35-70 5399

5400

HOLE #2 drilled 3rd.
Lunch.

START 12:20

0-35 - WASTE

35-70 - WASTE

FINISHED 1 12

0-35 - 5401

35-70 5402

HOLE #3.

START - 1:15

0-35 - waste.

35-70 very poor.

FINISHED 2:10

0-35' - 5403

35-70 - 5404

5405

Hole #5

START 2:45

0-35 - banded - poor
35-70 - banded - good ore
in bottom
25'

FINISHED 3:15

0-35' - 5406.
35-70 5407
5408.

Hole # ~~7~~
Started 3:20

0-35- poor (washed) (?)
35-70- good (light grade)

FINISHED 4:20
#

0-35 5409
35-70 5410
5411

2/10/9 #6
14003

0-25 - poor
25-35 - poor
35-41 - poor
41-71 - High grade

finished 10:50

0-25	5394	
25-35	5412	
35-71	5413	5413
	5415	5414

Hole # 8

Start 10⁵⁵.

0-35-

poor (waste)

35-51-

51-

Start - low grade ore
~~change~~

51-

0-35

- 5415

35-70

5416

51-70

5417

Wale #9

0-35 - waste

35-41 - Waste

41 - one

41-58 one

58-62 waste.

62-66 one

66 - waste

0-35 5418

35-70 5419

5420