



SEISMIC LINE 2
LOCATED 100 m UP
FARO VALLEY

LEGEND

- Present drainage channels from waste dump/Faro Valley
- - - Suggested rerouting of drainage channels
- Sump on 4030 bench
- - - Existing ditch
- - - Culvert
- - - Liner presently installed in ditch
- - - Reline ditch
- - - Clean ditch to bedrock and line
- - - Regrade ditch to prevent spillage to lower benches
- ▭ Regrade ponded area
- - - Location for proposed ditch
- Seismic profile
- ◆ Drillhole with piezometer
- Dewatering well
- ⊠ Abandoned test well
- Specific conductivity measurement
- Hydrogeological section (see Fig. 2)

ZONE I

SCALE 1" = 200'

CURRAGH RESOURCES LTD.

P PITEAU & ASSOCIATES
GEOTECHNICAL CONSULTANTS
VANCOUVER CALGARY

GROUNDWATER/SURFACE WATER
ASSESSMENT FOR ANVIL PIT
FARO, Y.T.

PLAN OF PIT AREA

A.H. Aug 86
OFF. FIG. 1

009048

