

~~1354~~ Corrections to K.A. surveying, u/g.

- 1) due to a surveying error on incline 2 N.E., the following DDHs (u/g) were recalculated. (co-ords & elevs)

u-36	u-74	u-123	u-133
u-37	u-76	u-127	u-136
u-38	u-78	u-131	u-137

u-141	u-159
u-143	u-161
u-147	

- 2) due to sign error on H.I., the following collar elevations were recalculated.

u-135	u-144	u-151
u-140	u-146	u-153
u-142	u-150	

- 3) due to sign error in H.P. of T.P. and H.I., the following collar elevs. were recalculated.

u-91	u-97	u-105
u-93	u-99	u-109
u-95	u-103	

- 4) u-105 and u-117 confused.

- 5) recalc. {dip} of u/g holes.
{az}

- a) u-146 Az is calculated wrong
- survey must be no good ∴ use layout az of 227°