

FARO DIVERSION

NORTH FORK

Seeps to Zone 2

Flows
Zinc loading mg/s

16 + 17 + 14 = 12 under by 0.7
9.7 1.8 0.6 1.9

12 + 11 = 10
1.9 9.9 11.44 over by 0.3

10 - loss = 9
11.44

9 + 7 + 8 = 3
8.1 3.72 1.22 22.26

3 + 4 + 5 + 6 = 23 PIT
22.3 5 4.1 19.6 36.1 over by 10.0

23 + gain = 2
36.1 37.6

2 + 31 = surface inflow
37.6 9.35 = 46.95

16 + 17 + 14 = 12

12 + 11 = 10

10 - loss = 9

9 + 7 + 8 = 3

3 + 4 + 5 + 6 = 23

23 + gain = 2

2 + 31 = surface inflow to Zone 2

