

ROCK CODE	DESCRIPTION
20	Ribbon banded graphitic quartzite
30	Pyritic quartzite
40	Semi-massive quartzose pyritic sulphides
50	Pyritic massive sulphides
60	Baritic massive sulphides
70	Pyrrhotitic massive sulphides
90	Fault breccia and gouge
100	Schist and phyllite waste
120	Altered schist and phyllite
170	Calc-silicate breccia
180	Biotite hornblende quartz diorite

- - - - June 1991 month end surface
—— Modified FIW ultimate pit
o—+ Monitoring prisms and movement direction
—— Faults

Monitor Scale 1 in. = 50 mm/day

inches 0 1 2
centimetres 0 1 2 3 4 5

This reference scale has been added to the original image. It will scale at the same rate as the image, therefore it can be used as a reference for the original size.

YUKON GEOLOGICAL SURVEY

QUICK-PLOT GEMCOM Services Inc.	DATE = 18-07-91 TIME = 21:32:22	CURRAGH RESOURCES INC. Faro Mine
HORIZONTAL SCALE = 1 : 600	VERTICAL SCALE = 1 : 600	

Section = 129_079 Outline = Lithology
NEW GEOLOGIC INTERPRETATION
EAST WALL MONITOR LOCATIONS - PROJECTED ONTO THE CLOSEST REPRESENATIVE SECTIONS.

019543