



ROCK CODE	DESCRIPTION
20	Ribbon banded graphitic quartzite
30	Pyritic quartzite
40	Semi-massive quartzose pyritic sulphides
50	Pyritic massive sulphides
60	Baritic massive sulphides
70	Pyrrhotitic massive sulphides
80	Fault breccia and gouge
100	Schist and phyllite waste
120	Altered schist and phyllite
170	Calc-silicate breccia
180	Biotite hornblende quartz diorite

- June 1991 month end surface
- Modified FIV ultimate pit
- Monitoring prisms and movement direction
- Faults

Monitor Scale 1 in. = 50 m/day

GUICK-PLOT GEMCOM Services Inc.	DATE = 16-07-91 TIME = 22:32:44	CURRAGH RESOURCES INC. Faro Mine	Section = 198,050 Outline = Lithology NEW GEOLOGIC INTERPRETATION EAST WALL MONITOR LOCATIONS - PROJECTED ONTO THE CLOSEST REPRESENTATIVE SECTIONS.
HORIZONTAL SCALE = 1 : 600		VERTICAL SCALE = 1 : 600	

019544