

ROCK CODE	DESCRIPTION
20	Ribbon banded graphitic quartzite
30	Pyritic quartzite
40	Semi-massive quartzose pyritic sulphides
50	Pyritic massive sulphides
60	Baritic massive sulphides
70	Pyrrhotitic massive sulphides
80	Fault breccia and gouge
100	Schist and phyllite waste
120	Altered schist and phyllite
170	Calc-silicate breccia
180	Biotite horablende quartz diorite

June 1991 month end surface
Modified FIV ultimate pit
Monitoring prisms and movement direction
Faults

Monitor Scale 1 in. = 50 mm/day

inches 0 1 2
0 1 2 3 4 5 centimetres
This reference scale bar is provided to ensure the original image is not misinterpreted when used as the image, therefore it may be smaller or larger than the original size.
YUKON GEOLOGICAL SURVEY

QUICK-PLOT GEMCOM Services Inc.	DATE = 18-07-91 TIME = 20:43:34	CURRAGH RESOURCES INC. Faro Mine
HORIZONTAL SCALE = 1 : 600	VERTICAL SCALE = 1 : 600	

Section = 119_050 Outline = Lithology
NEW GEOLOGIC INTERPRETATION
EAST WALL MONITOR LOCATIONS - PROJECTED ONTO THE CLOSEST REPRESENATIVE SECTIONS.

019547