

January 1989

Shovel 8

54	CD45B 15W	52.11	52.1	.13E+00	76340.	0.
52	CD45B 15S	36.96	89.1	.10E+01	23116.	31027.
61	CD45B 17C	10.93	100.0	.13E-01	15860.	157.

Waste 79430.  
 Calc-Silic 26396.  
 Sulph Wast 9490.

2BG	4.00-5.00	18098.
2BG	5.00-6.00	2826.
2BG	6.00+ .00	10260.

Shovel 7

41	CD45B 11R	90.54	90.5	.18E+00	75835.	0.
42	CD45B 11E	445.46	536.0	.69E+00	652601.	0.

Waste 728436.

Shovel 6

24	BZ 33-1	536.00	536.0	.62E+00	86770.	541422.
----	---------	--------	-------	---------	--------	---------

Waste 25761.  
 Sulph Wast 61010.

2BG	4.00-5.00	16707.
2BG	5.00-6.00	24508.
2BG	6.00+ .00	494717.
2A	6.00+ .00	5490.

FELoader (s

52	CD45B 15B	.00	.0	.10E+01	0.	0.
----	-----------	-----	----	---------	----	----

Total for: January 1989

Waste 833627.  
 Calc-Silic 26396.  
 Sulph Wast 70500.  
 2BG 4.00-5.00 34805.  
 2BG 5.00-6.00 27334.  
 2BG 6.00+ .00 504977.  
 2A 6.00+ .00 5490.

February 1989

Shovel 8

61	CD45B 17C	100.00	100.0	.13E+00	145061.	1439.
----	-----------	--------	-------	---------	---------	-------

Waste 144134.  
 Sulph Wast 927.

2BG	4.00-5.00	991.
2BG	6.00+ .00	448.

Shovel 7

42	CD45B 11E	15.25	15.2	.71E+00	22335.	0.
45	CD45B 13RE	116.54	131.8	.50E+00	97611.	0.
46	CD45B 13C	163.27	295.0	.28E+00	239186.	0.
50	CD45B 15RE	95.04	390.1	.50E+00	79610.	0.
51	CD45B 15C	95.91	486.0	.15E+00	140502.	0.

Waste 579244.

Shovel 6

24	BZ 33-1	233.30	233.3	.90E+00	37767.	235655.
25	BZ 34-1	252.70	486.0	.28E+00	64420.	231750.

Waste 24041.  
 Sulph Wast 78146.

2BG	4.00-5.00	21145.
2BG	5.00-6.00	33289.
2BG	6.00+ .00	410582.
2A	6.00+ .00	2389.

Total for: February 1989

Waste 747418.  
 Sulph Wast 79074.

13%

29 STAR

27 JAN

Favo wo

563816

2BG	4.00-5.00	22135.				
2BG	5.00-6.00	33289.				
2BG	6.00+ .00	411030.				
2A	6.00+ .00	2389.				

464,843

March 1989

Shovel 8

61 CD45B 17C	13.79	13.8	.15E+00	19999.	198.
--------------	-------	------	---------	--------	------

Waste 19871.

Sulph Wast 128.

2BG	4.00-5.00	137.			
-----	-----------	------	--	--	--

2BG	6.00+ .00	62.			
-----	-----------	-----	--	--	--

Shovel 7

51 CD45B 15C	121.05	121.0	.33E+00	177333.	0.
--------------	--------	-------	---------	---------	----

56 CD45B 16RE	28.43	149.5	.50E+00	23816.	0.
---------------	-------	-------	---------	--------	----

57 CD45B 16C	234.40	383.9	.30E+00	342655.	737.
--------------	--------	-------	---------	---------	------

60 CD45B 17RE	35.37	419.3	.50E+00	29630.	0.
---------------	-------	-------	---------	--------	----

61 CD45B 17C	74.83	494.1	<u>.24E+00</u>	108552.	1077.
--------------	-------	-------	----------------	---------	-------

63 CD45B 18RE	24.63	518.7	.50E+00	20629.	0.
---------------	-------	-------	---------	--------	----

64 CD45B 18C	17.29	536.0	.41E-01	13505.	975.
--------------	-------	-------	---------	--------	------

Waste 711549.

Calc-Silic 1677.

Sulph Wast 2895.

2BG	4.00-5.00	1009.			
-----	-----------	-------	--	--	--

2BG	5.00-6.00	190.			
-----	-----------	------	--	--	--

2BG	6.00+ .00	1589.			
-----	-----------	-------	--	--	--

Shovel 6

25 BZ 34-1	536.00	536.0	.88E+00	136638.	491554.
------------	--------	-------	---------	---------	---------

Waste 27209.

Sulph Wast 109428.

2BG	4.00-5.00	29425.			
-----	-----------	--------	--	--	--

2BG	5.00-6.00	47983.			
-----	-----------	--------	--	--	--

2BG	6.00+ .00	414146.			
-----	-----------	---------	--	--	--

FELoader (s

Total for: March 1989

Waste 758629.

Calc-Silic 1677.

Sulph Wast 112451.

2BG	4.00-5.00	30571.			
-----	-----------	--------	--	--	--

2BG	5.00-6.00	48173.			
-----	-----------	--------	--	--	--

2BG	6.00+ .00	415797.			
-----	-----------	---------	--	--	--

494,541

April 1989

Shovel 8

Shovel 7

64 CD45B 18C	352.69	352.7	<u>.88E+00</u>	275533.	19882.
--------------	--------	-------	----------------	---------	--------

65 CD45B 18W	167.31	520.0	.32E+00	245106.	0.
--------------	--------	-------	---------	---------	----

Waste 492354.

Sulph Wast 28284.

2BG	4.00-5.00	5462.			
-----	-----------	-------	--	--	--

2BG	5.00-6.00	3869.			
-----	-----------	-------	--	--	--

2BG	6.00+ .00	10551.			
-----	-----------	--------	--	--	--

Shovel 6

25 BZ 34-1	55.63	55.6	.94E+00	14182.	51020.
------------	-------	------	---------	--------	--------

26 BZ 35-1	464.37	520.0	.68E+00	115218.	429020.
------------	--------	-------	---------	---------	---------

Waste 37891.

Sulph Wast 91509.

2BG	4.00-5.00	50421.			
-----	-----------	--------	--	--	--

2BG	5.00-6.00	72802.			
-----	-----------	--------	--	--	--

2BG	6.00+ .00	356817.			
-----	-----------	---------	--	--	--

FELoader (s

Total for: April 1989

Waste		530246.			
Sulph Wast		119793.			
2BG	4.00-5.00		35883.		
2BG	5.00-6.00		76671.		
2BG	6.00+ .00		367368.		

479,922 \*

May 1989

Shovel 8

Shovel 7

65	CD45B 18W	355.26	355.3	.10E+01	520456.	0.
67	CD45B 19RE	28.17	383.4	.50E+00	23592.	0.
68	CD45B 19C	152.57	536.0	.61E+00	91046.	87771.

Waste 593227.

Sulph Wast 41867.

2BG 4.00-5.00 8021.

2BG 5.00-6.00 34469.

2BG 6.00+ .00 42910.

2A 6.00+ .00 2370.

Shovel 6

26	BZ 35-1	150.35	150.4	.90E+00	37306.	138910.
27	BZ 36-1	385.65	536.0	.82E+00	120907.	331070.

Waste 96364.

Sulph Wast 61848.

2BG 4.00-5.00 60959.

2BG 5.00-6.00 71140.

2BG 6.00+ .00 337881.

FELoader (s

Total for: May 1989

Waste 689591.

Sulph Wast 103715.

2BG 4.00-5.00 68980.

2BG 5.00-6.00 105610.

2BG 6.00+ .00 380790.

2A 6.00+ .00 2370.

~~429,000~~  
557,750

June 1989

Shovel 8

Shovel 7

68	CD45B 19C	96.59	96.6	.10E+01	57636.	55562.
69	CD45B 19W	423.41	520.0	.82E+00	616874.	3428.

Waste 649862.

Sulph Wast 24648.

2BG 4.00-5.00 5078.

2BG 5.00-6.00 25249.

2BG 6.00+ .00 27164.

2A 6.00+ .00 1501.

Shovel 6

27	BZ 36-1	59.28	59.3	.94E+00	18585.	50891.
28	BZ 37-1	289.92	349.2	.91E+00	99034.	240751.
71	CD45B 20RE	40.98	390.2	.50E+00	19024.	15298.
72	CD45B 20S	129.82	520.0	.47E+00	69377.	101796.

Waste 126539.

Sulph Wast 79481.

2BG 4.00-5.00 72641.

2BG 5.00-6.00 52668.

2BG 6.00+ .00 266709.

2A 6.00+ .00 16719.

FELoader (s

Total for: June 1989

Waste 776400.

Sulph Wast 104129.

2BG 4.00-5.00 77719.

467,727

2BG	5.00-6.00	77917.
2BG	6.00+ .00	293872.
2A	6.00+ .00	18219.

July 1989

Shovel 8

Shovel 7

69	CD45B 19W	116.72	116.7	.10E+01	170049.	945.
75	CD45B 21R	32.66	149.4	.50E+00	17347.	10011.
76	CD45B 21S	245.17	394.5	.10E+01	152539.	134794.
79	CD45B 22R	27.57	422.1	.50E+00	23089.	0.
80	CD45B 22S	113.89	536.0	.58E+00	62186.	71289.

Waste 356642.

Sulph Wast 68569.

2BG	4.00-5.00	34340.
2BG	5.00-6.00	14049.
2BG	6.00+ .00	154570.
2A	6.00+ .00	14081.

Shovel 6

72	CD45B 20S	146.21	146.2	.10E+01	78132.	114642.
73	CD45B 20W	389.79	536.0	.72E+00	539120.	31927.

Waste 560192.

Sulph Wast 57060.

2BG	4.00-5.00	16135.
2BG	5.00-6.00	22897.
2BG	6.00+ .00	88576.
2A	6.00+ .00	18960.

FELoader (s

Total for: July 1989

Waste 916833.

Sulph Wast 125629.

2BG	4.00-5.00	50475.
2BG	5.00-6.00	36947.
2BG	6.00+ .00	243146.
2A	6.00+ .00	33041.

363,609

August 1989

Shovel 8

Shovel 7

80	CD45B 22S	83.72	83.7	.10E+01	45712.	52404.
81	CD45B 22N	452.28	536.0	.94E+00	628568.	34027.

Waste 595055.

Sulph Wast 79226.

2BG	4.00-5.00	22054.
2BG	5.00-6.00	6117.
2BG	6.00+ .00	56469.
2A	6.00+ .00	1790.

Shovel 6

73	CD45B 20W	149.73	149.7	.10E+01	207096.	12264.
77	CD45B 21W	386.27	536.0	.77E+00	530901.	34979.

Waste 689430.

Sulph Wast 48567.

2BG	6.00+ .00	46360.
2A	6.00+ .00	883.

FELoader (s

Total for: August 1989

Waste 1284484.

Sulph Wast 127793.

2BG	4.00-5.00	22054.
2BG	5.00-6.00	6117.
2BG	6.00+ .00	102829.
2A	6.00+ .00	2673.

133,673

## September 1989

## Shovel 8

## Shovel 7

81	CD45B 22N	29.41	29.4	.10E+01	40868.	2212.
83	CD45B 23R	23.48	52.9	.50E+00	18682.	981.
84	CD45B 23S	274.35	327.2	.10E+01	162897.	158636.
85	CD45B 23N	192.77	520.0	.45E+00	232209.	50204.

Waste 363308.

Sulph Wast 91347.

2BG	4.00-5.00	8608.
2BG	5.00-6.00	7836.
2BG	6.00+ .00	191714.
2A	4.00-5.00	1906.
2A	6.00+ .00	1969.

## Shovel 6

77	CD45B 21W	117.41	117.4	.10E+01	161376.	10632.
81	CD45B 22N	.00	117.4	.10E+01	0.	0.
85	CD45B 23N	212.49	329.9	.95E+00	255962.	55339.
89	CD45B 24N	189.05	519.0	.10E+01	271009.	5946.
91	CD45B 25R	1.05	520.0	.22E-01	878.	0.

Waste 647224.

Sulph Wast 42001.

2BG	6.00+ .00	71665.
2A	6.00+ .00	253.

## FE Loader (s)

## Total for: September 1989

Waste 1010532.

Sulph Wast 133348.

2BG	4.00-5.00	8608.
2BG	5.00-6.00	7836.
2BG	6.00+ .00	263378.
2A	4.00-5.00	1906.
2A	6.00+ .00	2222.

283,950

## October 1989

## Shovel 8

## Shovel 7

85	CD45B 23N	19.72	19.7	.10E+01	23753.	5136.
88	CD45B 24R	28.06	47.8	.50E+00	18514.	4986.
87	CD45B 24S	480.02	527.8	.10E+01	186888.	446013.
96	CD45B 26E	8.21	536.0	.42E-01	4272.	6551.

Waste 172819.

Sulph Wast 60608.

2BG	4.00-5.00	7260.
2BG	5.00-6.00	9428.
2BG	6.00+ .00	437379.
2A	6.00+ .00	8620.

## Shovel 6

91	CD45B 25R	22.58	22.6	.50E+00	18913.	0.
92	CD45B 25NW	80.06	102.6	.10E+01	102912.	14378.
94	CD45B 25S	307.85	410.5	.10E+01	145890.	260012.
93	CD45B 25NE	125.51	536.0	.61E+00	139919.	43949.

Waste 266839.

Sulph Wast 140795.

2BG	4.00-5.00	33055.
2BG	5.00-6.00	12772.
2BG	6.00+ .00	249825.
2A	6.00+ .00	22686.

## FE Loader (s)

## Total for: October 1989

Waste 439658.

Sulph	Wast	201403.		
2BG	4.00-5.00		40315.	
2BG	5.00-6.00		22200.	
2BG	6.00+ .00		687204.	
2A	6.00+ .00		31306.	

281.025

November 1989

Shovel 8

Shovel 7

96	CD45B 26E	187.81	187.8	.10E+01	97740.	149893.
39	CD45B 9E	312.09	499.9	.10E+01	457215.	0.
38	CD45B 9R	20.09	520.0	.72E-01	16831.	0.

Waste 470596.

Sulph Wast 101189.

2BG	4.00-5.00	8131.
2BG	5.00-6.00	4085.
2BG	6.00+ .00	137677.

Shovel 6

93	CD45B 25NE	80.55	80.6	.10E+01	89802.	28207.
97	CD45B 26W	345.96	426.5	.10E+01	227007.	279827.
102	CD45B 27R1	93.49	520.0	.62E+00	45651.	32653.

Waste 292123.

Sulph Wast 70338.

2BG	4.00-5.00	3018.
2BG	5.00-6.00	13958.
2BG	6.00+ .00	287939.
2A	6.00+ .00	35771.

FELoader (s

Total for: November 1989

Waste 762719.

Sulph Wast 171527.

2BG	4.00-5.00	11150.
2BG	5.00-6.00	18042.
2BG	6.00+ .00	425616.
2A	6.00+ .00	35771.

490,579

December 1989

Shovel 8

Shovel 7

38	CD45B 9R	119.27	119.3	.50E+00	99900.	0.
144	D243 9	138.57	257.8	.10E+01	203009.	0.
41	CD45B 11R	278.16	536.0	.73E+00	232985.	0.

Waste 535894.

Shovel 6

102	CD45B 27R1	58.34	58.3	.10E+01	28490.	20378.
101	CD45B 27N	203.36	261.7	.10E+01	168999.	128919.
100	CD45B 27S	264.80	526.5	.10E+01	23266.	287078.
107	CD45B 28R1	9.50	536.0	.15E+00	6427.	1530.

Waste 147536.

Sulph Wast 79647.

2BG	4.00-5.00	10306.
2BG	5.00-6.00	15828.
2BG	6.00+ .00	402033.
2A	6.00+ .00	9739.

FELoader (s

Total for: December 1989

Waste 683431.

Sulph Wast 79647.

2BG	4.00-5.00	10306.
2BG	5.00-6.00	15828.
2BG	6.00+ .00	402033.
2A	6.00+ .00	9739.

487,906

January 1990						
Shovel 8						
Shovel 7						
41	CD45B 11R	135.81	135.8	.27E+00	113752.	0.
145	DZ43 11	207.64	343.4	.10E+01	304191.	0.
44	CD45B 13R2	192.55	536.0	.39E+00	161283.	0.
Waste		579226.				
Shovel 6						
107	CD45B 28R1	21.83	21.8	.35E+00	14766.	3515.
106	CD45B 28N	182.82	204.6	.10E+01	134743.	133090.
105	CD45B 28S	282.21	486.9	.11E+01	62958.	309142.
111	CD45B 29R1	39.96	526.8	.50E+00	6608.	26865.
110	CD45B 29C	9.18	536.0	.20E-01	2079.	8675.
Waste		142120.				
Sulph Wast		79033.				
2BG	4.00-5.00	23985.				
2BG	5.00-6.00	24455.				
2BG	6.00+ .00	413621.				
2A	5.00-6.00	281.				
2A	6.00+ .00	18946.				
FE Loader (s						
52	CD45B 15S	...	.0	.00E+00	...	0.

Total for: January 1990						
Waste		721347.				
Sulph Wast		79033.				
2BG	4.00-5.00	23985.				
2BG	5.00-6.00	24455.				
2BG	6.00+ .00	413621.				
2A	5.00-6.00	281.				
2A	6.00+ .00	18946.				

February 1990						
Shovel 8						
Shovel 7						
44	CD45B 13R2	297.89	297.9	.10E+01	249511.	0.
146	DZ43 13	188.11	486.0	.74E+00	275583.	0.
Waste		525095.				
Shovel 6						
110	CD45B 29C	442.90	442.9	.10E+01	100337.	418741.
29	CD45B 2 N	24.69	467.6	.29E+00	36164.	0.
115	CD45B 30R1	18.42	486.0	.35E+00	2270.	13155.
Waste		67982.				
Sulph Wast		70789.				
2BG	4.00-5.00	7312.				
2BG	5.00-6.00	13331.				
2BG	6.00+ .00	393283.				
2A	5.00-6.00	13559.				
2A	6.00+ .00	4411.				
FE Loader (s						

Total for: February 1990						
Waste		593076.				
Sulph Wast		70789.				
2BG	4.00-5.00	7312.				
2BG	5.00-6.00	13331.				
2BG	6.00+ .00	393283.				
2A	5.00-6.00	13559.				
2A	6.00+ .00	4411.				

March 1990						
Shovel 8						

27 J

90 STH

Favo wo

## Shovel 7

146	DZ43 13	64.84	64.8	.10E+01	74990.	0.
49	CD45B 15R2	457.07	521.9	.10E+01	382841.	0.
147	DZ43 15	14.09	536.0	.41E-01	20643.	0.

Waste 498475.

## Shovel 6

115	CD45B 30R1	7.72	7.7	.50E+00	951.	5513.
114	CD45B 30C	382.47	390.2	.10E+01	88457.	359801.
14	BZ 30-6	58.76	449.0	.47E+00	-390.	69257.
45	CD45B 13RE	87.05	536.0	.37E+00	72913.	0.

Waste 54120.

Sulph Waste 107810.

2BG	4.00-5.00	4298.
2BG	5.00-6.00	52006.
2BG	6.00+ .00	348106.
2A	6.00+ .00	30162.

FELoader (s

Total for: March 1990

Waste 552595.

Sulph Waste 107810.

2BG	4.00-5.00	4298.
2BG	5.00-6.00	52006.
2BG	6.00+ .00	348106.
2A	6.00+ .00	30162.

## April 1990

## Shovel 8

## Shovel 7

147	DZ43 15	326.15	326.2	.10E+01	477811.	0.
148	DZ43 17	193.85	520.0	.56E+00	283989.	0.

Waste 761800.

## Shovel 6

45	CD45B 13RE	29.49	29.5	.50E+00	24698.	0.
50	CD45B 15RE	95.04	124.5	.50E+00	79610.	0.
56	CD45B 16RE	28.43	153.0	.50E+00	23816.	0.
55	CD45B 16R2	134.69	287.7	.10E+01	112817.	0.
60	CD45B 17RE	35.37	323.0	.50E+00	29630.	0.
59	CD45B 17R2	196.97	520.0	.89E+00	164981.	0.

Waste 435552.

FELoader (s

Total for: April 1990

Waste 1197352.

-NO ore

## May 1990

## Shovel 8

## Shovel 7

148	DZ43 17	153.87	153.9	.10E+01	225423.	0.
149	DZ43 19	382.13	536.0	.83E+00	559817.	0.

Waste 743742.

Sulph Waste 41498.

## Shovel 6

59	CD45B 17R2	24.22	24.2	.10E+01	20290.	0.
63	CD45B 18RE	24.63	48.9	.50E+00	20629.	0.
62	CD45B 18R2	192.80	241.6	.10E+01	277824.	4621.
67	CD45B 19RE	28.17	269.8	.50E+00	23592.	0.
66	CD45B 19R2	266.19	536.0	.98E+00	346890.	43071.

Waste 663481.

Sulph Waste 25745.

2BG	4.00-5.00	4008.
2BG	5.00-6.00	4534.
2BG	6.00+ .00	39151.

FELoader (s

Total for: May 1990  
Waste 1407223.  
Sulph Wast 67243.  
2BG 4.00-5.00 4008.  
2BG 5.00-6.00 4534.  
2BG 6.00+ .00 39151.

47,693

June 1990

Shovel 8  
Shovel 7

149 DZ43 19 76.69 76.7 .10E+01 112349. 0.  
150 DZ43 21 443.31 520.0 .97E+00 636855. 12596.

Waste 677872.

Sulph Wast 71332.

2BG 4.00-5.00 7559.  
2BG 5.00-6.00 5037.

1st DZ ORE

Shovel 6

66 CD45B 19R2 4.32 4.3 .10E+01 5624. 698.  
71 CD45B 20RE 40.98 45.3 .50E+00 19024. 15298.  
70 CD45B 20R2 234.61 279.9 .10E+01 316624. 27080.  
75 CD45B 21R 32.66 312.6 .50E+00 17347. 10011.  
74 CD45B 21R2 207.43 520.0 .72E+00 266592. 37299.

Waste 526545.

Sulph Wast 98667.

2BG 4.00-5.00 5328.  
2BG 5.00-6.00 28435.  
2BG 6.00+ .00 56623.

FELoader (s

Total for: June 1990

Waste 1204417.

Sulph Wast 169999.

2BG 4.00-5.00 12887.  
2BG 5.00-6.00 33473.  
2BG 6.00+ .00 56623.

102,983

July 1990

Shovel 8

Shovel 7

150 DZ43 21 13.40 13.4 .10E+01 19252. 381.  
151 DZ43 23 522.60 536.0 .73E+00 472883. 292724.

Waste 436158.

Sulph Wast 55977.

2BG 4.00-5.00 114768.  
2BG 5.00-6.00 57932.  
2BG 6.00+ .00 120405.

2nd MONTH DZ OR

293,105

Shovel 6

74 CD45B 21R2 80.68 80.7 .10E+01 103689. 14507.  
79 CD45B 22R 27.57 108.2 .50E+00 23089. 0.  
78 CD45B 22R2 305.77 414.0 .10E+01 324912. 123040.  
83 CD45B 23R 23.48 437.5 .50E+00 18682. 981.  
82 CD45B 23R2 98.51 536.0 .33E+00 109781. 34536.

Waste 471747.

Sulph Wast 108405.

2BG 4.00-5.00 51603.  
2BG 5.00-6.00 21946.  
2BG 6.00+ .00 99516.

FELoader (s

Total for: July 1990

Waste 907905.

Sulph Wast 164383.

2BG 4.00-5.00 166371.

2BG 5.00-6.00 79878.  
 2BG 6.00+ .00 219921.

466170

August 1990

Shovel 8  
 Shovel 7

151 DZ43 23 197.61 197.6 .10E+01 178814. 110690.  
 152 DZ43 24 338.39 536.0 .93E+00 325786. 120376.

Waste 392472.  
 Sulph Wast 112129.

2BG 4.00-5.00 71580.  
 2BG 5.00-6.00 40881.  
 2BG 6.00+ .00 118605.

Shovel 6

82 CD45B 23R2 201.43 201.4 .10E+01 224476. 70619.  
 88 CD45B 24R 28.06 229.5 .50E+00 18514. 4986.  
 86 CD45B 24R2 275.88 505.4 .10E+01 217298. 186870.  
 91 CD45B 25R 23.63 529.0 .50E+00 19791. 0.  
 90 CD45B 25R2 7.00 536.0 .23E-01 5080. 5179.

Waste 360896.  
 Sulph Wast 124263.

2BG 4.00-5.00 29456.  
 2BG 5.00-6.00 15944.  
 2BG 6.00+ .00 222255.

FELoader (s

Total for: August 1990

Waste 753367.  
 Sulph Wast 236392.  
 2BG 4.00-5.00 101036.  
 2BG 5.00-6.00 56824.  
 2BG 6.00+ .00 340860.

490,720

September 1990

Shovel 8  
 Shovel 7

152 DZ43 24 23.68 23.7 .10E+01 22800. 8424.  
 153 DZ43 25 414.21 437.9 .10E+01 380890. 165251.  
 154 DZ43 26 82.10 520.0 .18E+00 71804. 36450.

Waste 276336.  
 Sulph Wast 199159.

2BG 4.00-5.00 57143.  
 2BG 5.00-6.00 22719.  
 2BG 6.00+ .00 130263.

Shovel 6

90 CD45B 25R2 296.23 296.2 .10E+01 214896. 219080.  
 98 CD45B 26R3 92.95 389.2 .10E+01 77798. 31136.  
 103 CD45B 27R3 107.64 496.8 .10E+01 76733. 49418.  
 107 CD45B 28R1 23.19 520.0 .72E+00 15686. 3734.

Waste 244745.  
 Sulph Wast 140368.

2BG 4.00-5.00 73577.  
 2BG 5.00-6.00 18781.  
 2BG 6.00+ .00 208958.  
 2A 6.00+ .00 2053.

FELoader (s

Total for: September 1990

Waste 521080.  
 Sulph Wast 339527.  
 2BG 4.00-5.00 130721.  
 2BG 5.00-6.00 41500.  
 2BG 6.00+ .00 339221.  
 2A 6.00+ .00 2053.

513,495

October 1990

Shovel 8

Shovel 7

154	DZ43 26	378.31	378.3	.10E+01	330857.	167950.
95	CD45B 26R2	157.69	536.0	.36E+00	82513.	49565.

Waste 180871.

Sulph Wast. 232499.

2BG 4.00-5.00 78383.

2BG 5.00-6.00 29520.

2BG 6.00+ .00 109611.

Shovel 6

107	CD45B 28R1	7.99	8.0	.85E+00	5408.	1288.
108	CD45B 28R3	80.04	88.0	.10E+01	45736.	48071.
111	CD45B 29R1	39.96	128.0	.10E+01	6608.	26865.
112	CD45B 29R3	140.31	268.3	.10E+01	62600.	101840.
109	CD45B 29R2	212.26	480.6	.10E+01	156387.	123485.
115	CD45B 30R1	26.13	506.7	.10E+01	3221.	18668.
116	CD45B 30R3	29.30	536.0	.15E+00	3376.	30960.

Waste 108879.

Sulph Wast 174457.

2BG 4.00-5.00 49096.

2BG 5.00-6.00 17725.

2BG 6.00+ .00 268720.

2A 6.00+ .00 15635.

FE Loader (s

Total for: October 1990

Waste 289750.

Sulph Wast 406956.

2BG 4.00-5.00 127480.

2BG 5.00-6.00 47245.

2BG 6.00+ .00 378331.

2A 6.00+ .00 15635.

569.691

November 1990

Shovel 8

Shovel 7

95	CD45B 26R2	278.35	278.3	.10E+01	145652.	87491.
155	DZ43 27	241.65	520.0	.49E+00	198164.	120456.

Waste 128795.

Sulph Wast 215021.

2BG 4.00-5.00 100085.

2BG 5.00-6.00 37775.

2BG 6.00+ .00 70088.

Shovel 6

116	CD45B 30R3	163.99	164.0	.10E+01	18897.	173299.
113	CD45B 30R2	195.56	359.5	.10E+01	130292.	98901.
119	CD45B 31R1	52.63	412.2	.10E+01	-1984.	46068.
118	CD45B 31C	107.82	520.0	.45E+00	19285.	107082.

Waste -15697.

Sulph Wast 182187.

2BG 4.00-5.00 21516.

2BG 5.00-6.00 34947.

2BG 6.00+ .00 337744.

2A 6.00+ .00 31144.

FE Loader (s

Total for: November 1990

Waste 113098.

Sulph Wast 397208.

2BG 4.00-5.00 121600.

2BG 5.00-6.00 72722.

2BG 6.00+ .00 407831.

633,297

2A 6.00+ .00 31144.

December 1990

Shovel 8

Shovel 7

155 DZ43 27	251.97	252.0	.10E+01	206622.	125598.
99 CD45B 27R2	257.69	509.7	.10E+01	245042.	132473.
156 DZ43 28	26.34	536.0	.60E-01	24509.	10225.

Waste 179303.

Sulph Wast 296870.

2BG 4.00-5.00	109682.
2BG 5.00-6.00	29653.
2BG 6.00+ .00	128959.

Shovel 6

118 CD45B 31C	132.92	132.9	.10E+01	23774.	132007.
22 BZ 31-7	120.58	253.5	.85E+00	52901.	88418.
120 CD45B 31R3	282.50	536.0	.95E+00	24215.	306878.

Waste -9360.

Sulph Wast 110250.

2BG 4.00-5.00	8208.
2BG 5.00-6.00	46070.
2BG 6.00+ .00	422300.
2A 6.00+ .00	50725.

FELoader (s

Total for: December 1990

Waste 169943.

Sulph Wast 407119.

2BG 4.00-5.00	117890.
2BG 5.00-6.00	75723.
2BG 6.00+ .00	551259.
2A 6.00+ .00	50725.

795,597

January 1991

Shovel 8

Shovel 7

156	DZ43 28	414.03	414.0	.94E+00	385204.	160701.
104	CD45B 28R2	121.97	536.0	.64E+00	94182.	84496.

Waste 106530.

Sulph Wast 372856.

2BG 4.00-5.00 27883.

2BG 5.00-6.00 63451.

2BG 6.00+ .00 153864.

Shovel 6

120	CD45B 31R3	14.94	14.9	.50E-01	1280.	16226.
117	CD45B 31R2	190.83	205.8	.10E+01	68162.	155490.
124	CD45B 32R1	57.75	263.5	.10E+01	-2177.	50551.
125	CD45B 32R3	260.83	524.3	.10E+01	28941.	276747.
121	CD45B 32RS	11.65	536.0	.26E+00	4912.	8747.

Waste 9135.

Sulph Wast 91984.

2BG 4.00-5.00 78386.

2BG 5.00-6.00 30480.

2BG 6.00+ .00 372582.

2A 6.00+ .00 26312.

FELoader (s

52	CD45B 15S	.00	.0	.00E+00	0.	0.
----	-----------	-----	----	---------	----	----

Total for: January 1991

Waste 115665.

Sulph Wast 464839.

2BG 4.00-5.00 106270.

2BG 5.00-6.00 93931.

2BG 6.00+ .00 526446.

2A 6.00+ .00 26312.

February 1991

Shovel 8

Shovel 7

104	CD45B 28R2	68.48	68.5	.10E+01	52884.	47445.
157	DZ43 29	417.52	486.0	.90E+00	428802.	121693.

Waste 90578.

Sulph Wast 391108.

2BG 4.00-5.00 54569.

2BG 5.00-6.00 15076.

2BG 6.00+ .00 99493.

Shovel 6

121	CD45B 32RS	32.46	32.5	.10E+01	13679.	24359.
123	CD45B 32C	164.18	196.6	.10E+01	-8173.	200597.
23	BZ 32-1	78.17	274.8	.95E-01	13321.	78293.
122	CD45B 32RN	28.01	302.8	.10E+01	1530.	31294.
24	BZ 33-1	67.67	370.5	.79E-01	10954.	68352.
127	CD45B 33C	115.52	486.0	.66E+00	-1724.	137110.

Waste -25699.

Sulph Wast 55286.

2BG 4.00-5.00 15142.

2BG 5.00-6.00 17489.

2BG 6.00+ .00 488155.

2A 6.00+ .00 19219.

FELoader (s

Total for: February 1991

Waste 64879.

Sulph Wast 446394.

2BG 4.00-5.00 69710.

2BG 5.00-6.00 32565.

27

91 STAR  
FARO WO

2BG	6.00+ .00	587648.
2A	6.00+ .00	19219.

March 1991

Shovel 8

Shovel 7

157	DZ43 29	48.14	48.1	.10E+01	49446.	14033.
158	DZ43 30	398.00	446.1	.10E+01	401033.	123730.
14	BZ 30-6	10.90	457.0	.87E-01	-72.	12852.
159	DZ43 31	78.95	536.0	.18E+00	66349.	37749.

Waste 44519.

Sulph Waste 472236.

2BG	4.00-5.00	36816.
2BG	5.00-6.00	42481.
2BG	6.00+ .00	108857.
2A	6.00+ .00	210.

Shovel 6

127	CD45B 33C	58.42	58.4	.10E+01	-872.	69340.
128	CD45B 33R2	171.57	230.0	.10E+01	51853.	149227.
126	CD45B 33R2	27.13	257.1	.10E+01	-1431.	33230.
25	BZ 34-1	45.71	302.8	.51E-01	11651.	41915.
130	CD45B 34C	122.90	425.7	.10E+01	14331.	129709.
131	CD45B 34R3	82.65	508.4	.10E+01	18103.	78766.
129	CD45B 34R2	27.62	536.0	.77E+00	-1457.	33824.

Waste -22360.

Sulph Waste 114540.

2BG	4.00-5.00	57729.
2BG	5.00-6.00	70577.
2BG	6.00+ .00	406204.
2A	6.00+ .00	1503.

FELoader (s

Total for: March 1991

Waste 22159.

Sulph Waste 586776.

2BG	4.00-5.00	94544.
2BG	5.00-6.00	113057.
2BG	6.00+ .00	515061.
2A	6.00+ .00	1714.

April 1991

Shovel 8

Shovel 7

159	DZ43 31	362.48	362.5	.10E+01	304622.	173314.
22	BZ 31-7	16.18	378.7	.11E+00	7098.	11863.
160	DZ43 32	141.34	520.0	.42E+00	130034.	56320.

Waste 74774.

Sulph Waste 366979.

2BG	4.00-5.00	50378.
2BG	5.00-6.00	42865.
2BG	6.00+ .00	147793.
2A	6.00+ .00	461.

Shovel 6

129	CD45B 34R2	8.08	8.1	.10E+01	-426.	9895.
26	BZ 35-1	42.62	50.7	.62E-01	10576.	39379.
133	CD45B 35C	90.53	141.2	.10E+01	24042.	82058.
134	CD45B 35F	22.47	163.7	.10E+01	4540.	21795.
132	CD45B 35R2	39.22	202.9	.10E+01	2692.	43274.
27	BZ 36-1	23.94	226.9	.51E-01	7506.	20552.
136	CD45B 36C	39.24	266.1	.10E+01	19001.	26983.
137	CD45B 36F	2.67	268.8	.10E+01	3131.	0.
135	CD45B 36R2	30.53	299.3	.10E+01	10978.	24806.
28	BZ 37-1	22.00	321.3	.69E-01	7515.	18268.
138	CD45B 37R2	22.50	343.8	.10E+01	8187.	18185.

SHVL # 6

139 CD45B 37C 24.12 367.9 .10E+01 18804. 9467.

Waste 51192.  
Sulph Waste 65353.  
2BG 4.00-5.00 81867.  
2BG 5.00-6.00 35078.  
2BG 6.00+ .00 197718.  
FELoader (s

Total for: April 1991

Waste 125966.  
Sulph Waste 432332.  
2BG 4.00-5.00 132246.  
2BG 5.00-6.00 77943.  
2BG 6.00+ .00 345511.  
2A 6.00+ .00 461.

May 1991

Shovel 8

Shovel 7

160 DZ43 32 196.92 196.9 .10E+01 181168. 78467.  
161 DZ43 33 297.92 494.8 .10E+01 295091. 97720.  
24 BZ 33-1 20.58 515.4 .10E+00 3332. 20791.  
162 DZ43 34 20.58 536.0 .73E-01 17367. 6748.

Waste 105724.

Sulph Waste 391235.  
2BG 4.00-5.00 42387.  
2BG 5.00-6.00 16400.  
2BG 6.00+ .00 144730.  
2A 6.00+ .00 211.

Shovel 6

FELoader (s

Total for: May 1991

Waste 105724.  
Sulph Waste 391235.  
2BG 4.00-5.00 42387.  
2BG 5.00-6.00 16400.  
2BG 6.00+ .00 144730.  
2A 6.00+ .00 211.

June 1991

Shovel 8

Shovel 7

162 DZ43 34 262.05 262.1 .10E+01 221181. 85946.  
25 BZ 34-1 4.29 266.3 .56E-01 1094. 3937.  
163 DZ43 35 253.65 520.0 .87E+00 172747. 124534.

Waste 44688.

Sulph Waste 350335.  
2BG 4.00-5.00 236.  
2BG 5.00-6.00 384.  
2BG 6.00+ .00 213797.

Shovel 6

FELoader (s

Total for: June 1991

Waste 44688.  
Sulph Waste 350335.  
2BG 4.00-5.00 236.  
2BG 5.00-6.00 384.  
2BG 6.00+ .00 213797.

July 1991

Shovel 8

Shovel 7							
163	DZ43 35	38.86	38.9	.10E+01	26466.	19079.	
26	BZ 35-1	26.75	65.6	.10E+00	6637.	24715.	
164	DZ43 36	223.18	288.8	.10E+01	14294.	247270.	
27	BZ 36-1	4.26	293.0	.60E-01	1335.	3656.	
165	DZ43 37	195.13	488.2	.10E+01	41587.	187103.	
28	BZ 37-1	7.38	495.6	.92E-01	2519.	6125.	
166	DZ43 38	40.45	536.0	.41E+00	12728.	34678.	

Waste	49496.						
Sulph Waste	56071.						
2BG	4.00-5.00	21011.					
2BG	5.00-6.00	41718.					
2BG	6.00+ .00	459896.					

Shovel 6  
FE Loader (s)

Total for: July 1991

Waste	49496.						
Sulph Waste	56071.						
2BG	4.00-5.00	21011.					
2BG	5.00-6.00	41718.					
2BG	6.00+ .00	459896.					

August 1991

Shovel 8							
Shovel 7							
166	DZ43 38	57.50	57.5	.10E+01	18094.	49298.	

Waste	15735.						
Sulph Waste	2359.						
2BG	6.00+ .00	49298.					

Shovel 6  
FE Loader (s)

Total for: August 1991

Waste	15735.						
Sulph Waste	2359.						
2BG	6.00+ .00	49298.					

September 1991

Shovel 8  
Shovel 7  
Shovel 6  
FE Loader (s)

Total for: September 1991

October 1991

Shovel 8  
Shovel 7  
Shovel 6  
FE Loader (s)

Total for: October 1991

November 1991

Shovel 8  
Shovel 7  
Shovel 6  
FE Loader (s)

Total for: November 1991

December 1991

Shovel 8  
Shovel 7  
Shovel 6  
FE Loader (s)

Total for: December 1991

SHVL #7

Fi