

Generally mining has been in an area of marginal, and lower than average density, drilling. Together with structural variations (fold wavelengths) less than average drill spacing it has meant that the original geological interpretation has suffered in accuracy.

A significant part of the Pb grade difference for Panway is simply due to an area of relatively high grade ground being mined that was not predicted at all by the model.

Poor drill core recovery over part of the deposit have not helped predictability.