



1210
1205
1200
1195
1190
1185
1180
1175
1170
1165
1160



12 03 75 REVISED CURVE DUE TO BAD GROUND CONDITION R.W.			
NO.	DATE	REVISION	BY
CANADIAN MINE SERVICES LTD. VANCOUVER, B.C. CANADA			
GRUM JOINT VENTURE KERR ADDISON MINES Ltd DECLINE ACCESS - 12%			
DESIGNED	CMS	BILL OF MAT'L	DATE Sept 5/75
DRAWN	Active	JOB NO. 666	SCALE 1:250 m.
TRACED			Dwg. No. 666-405
CHECKED	008353		Rev. 1



Handwritten note: 21° 04' 41" @ 75-022
Sill at 1172.3