

# D.J.B. Services Ltd.

Geological - Administrative Consultants

47 - 12<sup>th</sup> Ave  
Whitehorse, Yukon  
Y1A 4J7

---

## Geological Drill Core Logs from A. Carlos; Ran Property, Ross River Area, Yukon

D.J.B. Services geologically logged core from three diamond drill holes on August 12<sup>th</sup>, 1995. The core is from A. Carlos' Ran property near Ross River, Yukon.

**DDH #1** This core has been completely split and analyzed for Au, Ag, Cu, Pb, Zn, Mo, Bi, As, Sb and Hg (report attached).

0-60 feet Overburden

60-127 feet Argillite; highly brecciated and crushed (mechanical clay gouge present) in part calcareous and carbonaceous argillite. 60 to 103 feet the argillite is a lightish blue grey weathered colour and from 103 to 127 feet a dark bluish black colour.

105.8 to 106 feet the argillite is a creamy white colour due to extensive argillic (clay) alteration. This alteration is present throughout the argillic section (generally patchy and in bands  $\leq 0.25$  inches).

The entire zone has  $\leq 0.25\%$  disseminated pyrite +/- tetrahedrite and chalcopyrite (from Vancouver Petrographics Ltd. report, attached).

127-136 feet Diorite; a pale greenish carbonate altered fine grained microdiorite with disseminated pyrite ( $\leq 0.5\%$ ) and trace chalcopyrite (from Vancouver Petrographics Ltd. report). Most likely a dike or sill. EOH.