



# Field Report

(167070007)

Started Oct. 10.....1989

Completed Oct. 11.....1989

PH. 633-3070 TELEX 036-8496

P.O. BOX 4391

WHITEHORSE, YUKON

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
Glavia Johnson	W/W	
	89-1A-40	Destruction Bay

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE				
			LOADING	Oct. 10	8:00	11:30	3.5
			TRAVELING	"	11:30	3:30	4
			START #69	"	3:30	4:00	0.5
			MOVE ON SET UP	"	4:00	5:00	1
0	10	silt	Gr. sand.	"	5:00	7:00	2.
10	46	silt	Gr. Clay				
46	60	till					
60	79	till		Oct. 11	8:00	9:30	1.5
79	85	Gr.	sand silt				
			set screen Develop	"	9:30	1:00	3.5
			move off.	"	1:00	1:30	0.5

Rcprd. of Casing & Pipe

Size	Type	Size	Type
------	------	------	------

Remarks:

6			
Feet	Inch	Feet	Inch

83	6		
----	---	--	--

1-6" odex shoe (ss)  
20 slot  
5 7/8" bit pin  
3" riser-K Packer  
20 GPM.

Static Level		Total Rig Time	hrs.
Ground Level	8'	Total Standby	hrs.
Top Of Casing		Drilling Mud	sacks

SIGNATURES

MIDNIGHT SUN.....

CLIENT.....

TITLE.....

TITLE.....