





# Field Report 107071014

13 MacDONALD ROAD  
WHITEHORSE, YUKON  
Y1A 4L1

Started...S.E.P.T...27...19.93

Completed...O.C.T...2.....19....

PHONE (403) 633-3070  
TELEX 036-8496

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
Public Works Canada 204 Ranger Road RALPH ZACCARIELLI	W/W 93-1A-17	Health center Destruction Bay Dredging work

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE				
			Loading	sept. 27	8:00	12:00	4
			Travel	"	1:00	5:00	4
			remove fence	"	5:00	5:30	0.5
			move on set up	"	5:30	7:30	2
			Disconnect pump ready to pull				
			Pull pump	sept. 28	8:00	8:30	0.5
			Pull casing Redrill to 60' Trouble Plugging + closing bit	"	8:30	7:30	11
			Redrill to 83'	sept 29	8:00	9:00	1
83	89	Gr.	sand silt	"	9:00	7:00	10
89	154	till					
54	161	silt	Gr. sand				
161	177	clay					
77	198	silt	clay Gr.				
98	226	till	with silt clay + Gr. layers				

ord. of Casing & Pipe				Remarks:	
Size	Type	Size	Type		
Feet	Inch	Feet	Inch		
Static Level				Total Rig Time	hrs.
Ground Level				Total Standby	hrs.
Top Of Casing				Drilling Mud	sacks

SIGNATURES

MIDNIGHT SUN.....  
TITLE.....

CLIENT.....  
TITLE.....