Field Report

109010055

MIDNIGHT SUN DRILLING CO. LTD.
WHITEHORSE Y.T.
PH. 633-3070
P.O. BOX 4391
WHITEHORSE, YUKON

Started. Nov. 17 ..... 19 86

Completed. Nov. 17 ..... 19 86

(3)

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
Randy Taylor	W/W.	Hordenskiold sub. Lot # 106 carmacks

FORMATION LOG FROM	TO	FORMATION	DESCRIPTION OF WORK	TIME DATE	FROM	TO	HOURS
			MOVE				
			move set up.	Nov. 17	6:30	9:00	2.5
0'	27'	Gr. sand cob. silt		"	9:00	2:30	5.5
27'	52	sand.					
52	61	sand	some Gr.				
			Trouble with casing hammer				
			set 10 slot screen	"	2:30	3:00	0.5
			Develop	"	3:00	4:30	1.5
			move to lot in town	"	4:30	5:30	1
			casing hammer not working	"	5:30	8:00	2.5
			Travel to Whitehorse.	"	8:00	10:30	2.5

Rcrd. of Casing & Pipe Size	Type	Size	Type
Feet	Inch	Feet	Inch
58			

Remarks:

1- Drive shoe.
2'-riser lead packer
1- 5 7/8" bit pin
10 slot screen.
screen bottom 61'

Static Level	Total Rig Time hrs.
Ground Level 47	Total Standby hrs.
Top Of Casing	Drilling Mud sacks

SIGNATURES

MIDNIGHT SUN ..... Leo .....

TITLE .....

CLIENT .....

TITLE .....

Willow Printers