



Field Report

(109150035)

13 MacDONALD ROAD
WHITEHORSE, YUKON
Y1A 4L1

PHONE (403) 633-3070
TELEX 036-8496

Started *Sept. 6*.....19*88*.

Completed *Sept. 6*.....19*88*.

②

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
<i>Selkirk Indian Band Pelly</i>	<i>W/W</i>	<i>House #49</i>
	<i>88-1A-33</i>	<i>Tommy McInty</i>

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			<i>MOVE</i>				
<i>0</i>	<i>5</i>	<i>silt</i>		<i>Sept 6</i>	<i>4:30</i>	<i>6:30</i>	<i>2</i>
<i>5</i>	<i>45</i>	<i>sand Gr. Cobs.</i>					
			<i>set screen Developer</i>	<i>11</i>	<i>6:30</i>	<i>8:30</i>	<i>2</i>

Rcd. of Casing & Pipe

Size	Type	Size	Type
<i>6</i>			
<i>Feet</i>	<i>Inch</i>	<i>Feet</i>	<i>Inch</i>
<i>43</i>			

Remarks:

1 - shoe
15 slot screen
2' riser - packer & bottom
6 GPM.

Static Level	Total Rig Time	hrs.
Ground Level <i>33'</i>	Total Standby	hrs.
Top Of Casing	Drilling Mud	sacks

SIGNATURES

MIDNIGHT SUN.....

TITLE.....

CLIENT *Tommy McInty*

TITLE.....

Dan Van Ribber