MIDNIGHT SUN DRILLING CO. LTD.
PH: 668-2434
WHITEHORSE Y.T.
P.O. Box 4391

FIELD REPORT

201020072

Started.. May 23 .....19 77.
Completed. May 23 .....19 77.

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
Stanley and Associates	Test Hole #2	Watson Lake

FORMATION LOG FROM	TO	FORMATION	DESCRIPTION OF WORK	TIME DATE	FROM	TO	HOURS
			MOVE				
0'	5'	sand and gravel	drilling to 108'	May23	12;30	5:30	5
5'	7'	black rock					
7'	24'	silty sand till					
24'	75'	silt, cream brown					
75'	108'	silt brown					

Rcrd. of Casing & Pipe

Size	Type	Size	Type
Feet	Inch	Feet	Inch

Remarks:
~~0' 15' 6¼~~
15' 21' 4 7/8 wing
21' 30' 4 7/8
30' 108' 4 7/8 wing

STATIC LEVEL	Total Rig Time 5 hrs.
Ground level	Total Standby hrs.
Top of casing	Drilling Mud 2 sacks

SIGNATURES

MIDNIGHT SUN.....Merv Tull.....
TITLE.....

CLIENT.....
TITLE.....