



# Field Report

201020076

Started June 19.....1991

Completed June 20.....1991

PH. 633-3070 TELEX 036-8496  
P.O. BOX 4391  
WHITEHORSE, YUKON

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
own of Watson Lake	Water well 91-1A-12	Lucky Lake

FORMATION LOG			DESCRIPTION OF WORK	DATE	TIME		HOURS
FROM	TO	FORMATION			FROM	TO	
			MOVE				
			move on set up	June 19	4:30	6:00	1.5
				"	6:00	9:00	3
0	36	fine sand					
36	53	fine sand silt					
53	74	Brown silt					
74	100	Grey silt					
				June 20	7:30	12:00	4.5
100	132	Grey silt					
132	137	silt clay					
137	144	silt sand Gr.					
144	155	Gr. sand fine sand some silt		"	12:00	1:00	1
		set screen		"	1:00	3:00	2
		Developers		"	3:00	4:30	1.5
		move off. to Watson					

Rcd. of Casing & Pipe			
Size	Type	Size	Type
Feet	Inch	Feet	Inch
6			
153	6		

Remarks: 25 GPM  
1- odet shoe  
20 slot screen  
K packer  
5 7/8" bit pin  
155' screen bottom

Static Level	Total Rig Time	hrs
Ground Level	Total Standby	hrs.
Top Of Casing	Drilling Mud	sack

SIGNATURES  
CLIENT: *Mr. Robinson*  
TITLE: P.O. # 0046

MIDNIGHT SUN.....  
TITLE.....