



Field Report

PH. 633-3070 TELEX 036-8496
 P.O. BOX 4391
 WHITEHORSE, YUKON

201020138
~~# 201020138~~

Started May 8th 1991

Completed.....19....

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
Kilborn Eng.	water well TH # 3	

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE				
0	8	Gr.	sand silt	May 8	7:00	2:00	7
8	11	silt					
11	34	Gr.	sand silt				
34	58	silt	Gr. sand				
58	70	Gr.	sand silt				
70	82	silt	Gr. sand				
82	96	Gr.	sand some silt				
96	97	silt	fine sand Gr.				
			Cutting off shoe	11	2:00	4:00	2
			set screen at 94'	11	4:00	5:00	1
			Develop	11	5:00	5:30	0.5
			move off	11	5:30	7:00	1.5

Rcd. of Casing & Pipe			
Size	Type	Size	Type
6 5/8			
Feet	Inch	Feet	Inch
92'			

Remarks:	
1 - o.d. shoe.	
2' locking cap	
Name Plate	
2 - 25 slot screens	
1 - screen bottom	
1 - K Packer.	
Static Level	Total Rig Time hrs.
Ground Level	Total Standby hrs.
Top Of Casing	Drilling Mud sacks

SIGNATURES

MIDNIGHT SUN.....
 TITLE.....

CLIENT... *W. Hainy...* KILBORN INC
 TITLE..... *ENGINEER*.....