Field Report

#20102014 3

Started May 5 19 91

Completed ..... 19....

MIDNIGHT SUN DRILLING CO. LTD. WHITEHORSE Y.T.
PH. 633-3070 TELEX 036-8496
P.O. BOX 4391
WHITEHORSE, YUKON

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
Kilborn Eng.	water well TH # 8	

FORMATION LOG FROM	TO	FORMATION	DESCRIPTION OF WORK	TIME DATE	FROM	TO	HOURS
			MOVE				
			move set up	May 12	5:00	6:00	1
0	15	Gr.	sand silt	May 13	7:00	9:00	2
15	29	silt	Gr. sand.				
29	34	silt	Clay Gr.				
34	40	Till	(grey)				
			Fix rubber in diverter	"	9:00	10:00	1
			Pull casing	"	10:00	10:30	0.5

Rcrd. of Casing & Pipe Size	Type	Size	Type
Feet	Inch	Feet	Inch

Remarks:

Static Level	Total Rig Time hrs.
Ground Level	Total Standby hrs.
Top Of Casing	Drilling Mud sacks

SIGNATURES

MIDNIGHT SUN.....

TITLE.....

CLIENT. [signature]

TITLE... Engineer

Willow Printers