



# Field Report

PH. 633-3070 TELEX 036-8496  
 P.O. BOX 4391  
 WHITEHORSE, YUKON

# 201020146

Started May 4<sup>th</sup> 5<sup>00</sup> 1991

Completed.....19....

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
Kilborn Eng.	water well TH #11	

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE				
			move set up	May 14	11:00	1:00	2
			Fix Divertor	"	1:00	2:00	1
0	17	Gr	sand silt	"	2:00	3:30	1.5
17	29	silt	Gr. sand				
29	31	silt	fine sand				
31	39	Gr.	sand silt				
39	40	Till	(gr)				
			set screen	"	3:30	4:00	0.5
			Develop	"	4:00	5:30	1.5

Crd. of Casing & Pipe				Remarks:
Size	Type	Size	Type	
6 5/8				1- odax shoe
Feet	Inch	Feet	Inch	25 slot screen
35	6			screen bottom
				K Packer
				2' locking cap
				Name Plate
				Static Level
				Ground Level
				Top Of Casing
				Total Rig Time
				Total Standby
				Drilling Mud

SIGNATURES

MIDNIGHT SUN.....  
 TITLE.....

CLIENT. W. Hamp  
 TITLE... Engineer