



Field Report

PH. 633-3070 TELEX 036-8496
 P.O. BOX 4391
 WHITEHORSE, YUKON

#201020152 Started May 5 1991
 Completed.....19....

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
Kilborn Eng.	water well TH # 17	

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE				
			move set up	May 23	1:30	3:30	2
2	16	Gr.	sand silt	"	3:30	7:30	4
2	22	silt	Clay Gr.				
2	54	silt	sand Gr.				
4	76	till	(brown)				
6	80	silt	Gr. sand.				
0	93	silt	Gr. sand	May 24	6:30	2:00	7.5
3	106	silt	sand Gr.				
6	131	Gr.	sand silt				
1	137	fine	sand silt some Gr.				
37	142	Gr	sand silt				
42	173	Gr	sand some silt				
23	175	BR.					
			cutting off shoe	"	2:00	3:00	1
			set screens	"	3:00	4:00	1
			Develop.	"	4:00	5:30	1.5

d. of Casing & Pipe				Remarks:		
Size	Type	Size	Type			
58				1- casing cut.		
				1- odex shoe		
feet	Inch	Feet	Inch	2- 20 slot screens		
69				screen bottom		
				2' visex pipe		
				K Packer		
				2' locking cap.		
				Name Plate		
				Static Level	Total Rig Time	hrs.
				Ground Level	Total Standby	hrs.
				Top Of Casing	Drilling Mud	sacks

SIGNATURES

MIDNIGHT SUN.....
 TITLE.....

CLIENT... KILBORN
 TITLE... W. Hays