



Field Report

13 MacDONALD ROAD #201020166
 WHITEHORSE, YUKON
 Y1A 4L1
 PHONE (403) 633-3070
 TELEX 036-8496

Started... Aug... 24... 1990
 Completed... Aug... 26... 1990

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
Klahn Leonoff		Watson lake
	90-1A-34	

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE				
			Travel to Watson Lake	Aug 24	6:30	2:00	7.5
			move on set up	"	3:00	6:30	3.5
0	7	silt		"	6:30	8:00	1.5
7	15	silt	some Gr.				
15	18	silt					
18	70	till	cobbles				
70	75	till	cobbles				
75	108	BR					
108	109	silt	Layer				
109	121	BR					
121	134	Broken BR	some Gr.				
134	165	Gr.	sand silt cobbles				
165	222	silt	Clay				
222	233	Gr	sand silt clay				
233	256	silt	clay				
256	274	sand	Gr.				
274	277	silt					

Rcd. of Casing & Pipe				Remarks:		
Size	Type	Size	Type			
Feet	Inch	Feet	Inch			
				Static Level	Total Rig Time	hrs.
				Ground Level	Total Standby	hrs.
				Top Of Casing	Drilling Mud	sacks

SIGNATURES

MIDNIGHT SUN.....
 TITLE.....

CLIENT.....
 TITLE.....

