

FIELD REPORT



P.O. Box 4391

Started..May.21.....19.77.

Completed..May.21.....19.77.

201020185

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
Stanley and Associates 212-212 Main St. Whitehorse, Y.T.	Test Hole #1 For the town of Watson Lake, Y.T.	Watson Lake, Y.T.

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE				
0'	7'	gravel, rocks		May21	7:30	7pm	11.5
7'	37'	gravel, silty sand, till					
37'	44'	silt (brown)					
44'	128'	silt and fine sand					
128'	139 1/2'	peat					
139 1/2'	141'	rock, green silt					
141'	155'	till, clay, sand					
			Maye to #32 w/w	May22/77	7:00	8:00	1.0

Rcrd. of Casing & Pipe				Remarks:
Size	Type	Size	Type	
Feet	Inch	Feet	Inch	

STATIC LEVEL	Total Rig Time	11.5	hrs.
Ground level	Total Standby		hrs.
Top of casing	Drilling Mud	6	sacks

SIGNATURES

Merv Tull
MIDNIGHT SUN.....
TITLE.....

CLIENT.....
TITLE.....