



Field Report

PH. 633-3070 TELEX 036-8496
P.O. BOX 4391
WHITEHORSE, YUKON

201020193

Pg. 2

Started June 5... 1991

Completed June 11... 1991

②

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
SA Pena Hes Joint Ventures	water well Hole #1 91-1A-9	CRD Watson Lake - TRUCK TERMINAL

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE				
			Loading	June 7	9:00	11:00	2
			Travel to Watson	June 10	8:00	3:00	7
			Spotting Air Port site	"	4:00	5:00	1
			Trip out	"	6:30	7:00	0.5
			Cutting off shoe	"	7:00	8:30	1.5 ^{SA}
			setting screen	June 11	7:00	9:30	2.5 ^A
			Developing	"	9:30	6:30	9 ^A
			move off	"	6:30	8:00	1.5 ^{SA}

crd. of Casing & Pipe				Remarks:		
Size	Type	Size	Type			
6"				116' 6" bottom of screen (open)		
Feet	Inch	Feet	Inch	1- drive shoe.		
				1- 20 slot screen		
117'				1- 2" riser pipe		
				2- K Packers		
				5' x 5 1/8" stand pipe		
				1- casing cut.		
				Static Level	Total Rig Time	hrs.
				Ground Level 65' 6"	Total Standby	hrs.
				Top Of Casing	Drilling Mud	sacks

SIGNATURES

MIDNIGHT SUN.....
TITLE.....

CLIENT [Signature].....
TITLE SR. PROJ. ENGINEER.....