



Field Report

13 MacDONALD ROAD
WHITEHORSE, YUKON
Y1A 4L1

PHONE (403) 633-3070
TELEX 036-8496

Started. July 28... 1992

Completed. July 31... 1992

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
Harry Madson	W/W	Carecross Rd.
	92-1A-22	

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE				
			crew travel	July 30	8:00	9:00	1
290	297	Brownish Grey Hard		"	9:00	3:30	6.5
297	305	Dark Green					
305	329	Brownish Grey Green Hard					
329	389	Green white					
389	395	black & Brown shale.					
395	406	Black shale.		"	8:30	10:00	7.5
406	408	Grey					
408	413	Black					
413	414	Grey					
414	453	Black					
453	454	Grey Brown					
454	473	Black					
473	486	Grey Brown					
486	494	Black					
494	500	Brown Black Grey					
			crew travel	"	10:00	11:00	1

Rcd. of Casing & Pipe

Size	Type	Size	Type

Remarks:

Feet	Inch	Feet	Inch

Static Level	Total Rig Time	hrs.
Ground Level	Total Standby	hrs.
Top Of Casing	Drilling Mud	sacks

SIGNATURES

MIDNIGHT SUN.....

CLIENT.....

TITLE.....

TITLE.....

