



Field Report

B:ID 204080002

PH. 633-3070 TELEX 036-8496
P.O. BOX 4391
WHITEHORSE, YUKON

Started Oct. 7.....1988

Completed Oct. 7.....1988

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
Bill Doyle.	W/W	Lot #69 Judas Creek sub Div.
	88-1A-41	

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE				
			loading	Oct. 7	8:00	9:00	1
			move on set up	"	9:00	11:30	2.5
0	6	sand	br. silt	"	11:30	3:00	3.5
6	12	clay					
12	18	fine	silty sand.				
18	23	fine	sand				
23	34	sand	br. cobs. silt				
34	47	fine	silty sand.				
47	81	fine	to coarse sand.				
			some silt				
			set screen Develop	"	3:00	5:30	2.5
			move off	"	5:30	6:00	0.5
			crew travel.	"	6:00	7:00	1

Rcrod. of Casing & Pipe				Remarks:
Size	Type	Size	Type	
6"				1- shoe
Feet	Inch	Feet	Inch	15 slot screen
79				2' riser lead Packer
				5 7/8" bit pin
				5 GPM.
				Static Level
				Ground Level 58'
				Top Of Casing
				Total Rig Time hrs.
				Total Standby hrs.
				Drilling Mud sacks

SIGNATURES

MIDNIGHT SUN... has.....
TITLE..... Travis.....
Carl - 3 hrs.

CLIENT. Bill Doyle.....
TITLE.....