Field Report

B·ID 204080004

MIDNIGHT SUN DRILLING CO. LTD. WHITEHORSE Y.T.

13 MacDONALD ROAD
WHITEHORSE, YUKON
Y1A 4L1

PHONE (403) 633-3070
TELEX 036-8496

Started June 19 1990

Completed June 21 1990

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
Conrad Boyce	W/W	Lot 122 - Judas Creek
Box 3954		subdiv.
Y1A 5M6	90-1A-20	

FORMATION LOG FROM	TO	FORMATION	DESCRIPTION OF WORK	TIME DATE	FROM	TO	HOURS
			MOVE				
			move on setup	June 19	8:00	11:00	3
0	7	Gr.	sand.	"	11:00	5:00	6
7	11	silt					
11	97	Gr.	sand				
97	120	Gr.	sand silt				
			Broke off casing shoe.				
			crew travel	"	5:00	6:00	1
			crew travel	June 20	8:00	9:00	1
			Pull casing	"	9:00	12:00	3
			Redrill to 120'	"	12:00	5:30	5.5
120	124	Gr.	sand silt				
124	127	Clay					
			crew travel	"	5:30	6:30	1
			crew travel	June 21	8:00	9:00	1
			set screen	"	9:00	10:00	1
			Develop	"	10:00	1:00	3
			move off to shop	"	1:00	3:30	2.5

Rcrd. of Casing & Pipe Size	Type	Size	Type
6			
Feet	Inch	Feet	Inch
123'			

Remarks: Lost 1- odex shoe
1- odex shoe.
25 slot - K Packer
5 7/8" bit pin
10 -GPM
screen bottom 124'

Static Level		Total Rig Time	hrs.
Ground Level	96'	Total Standby	hrs.
Top Of Casing		Drilling Mud	sacks

SIGNATURES

MIDNIGHT SUN..... CLIENT.....

TITLE..... TITLE.....

Willow Printers