

105 D 08



Field Report

204080032

13 MacDONALD ROAD
WHITEHORSE, YUKON
Y1A 4L1

540 350
6704 015 t
30/100m

Started Aug. 28.....1988

Completed Aug. 30.....1988

PHONE (403) 633-3070
TELEX 036-8496

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
Terry Demianenko 160 S. Ellesmere Ave Burnaby BC.	W / W 88-1A-30A	Lot #18 ^{New} Constabular sub. div.

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE				
			Travel from Atlin	Aug 28	8:30	11:00	2.5
			Change over	"	11:00	1:00	2
0	6	silt	sand Gr.	Aug 28	1:00	7:30	6.5
6	27	till	Cobbles				
27	34	silt	Gr.				
34	48	silt	sand Gr.				
48	120	till	Cobbles silt + Gr. Layers				
120	167	till	Cobbles silt & Gr Layers	Aug 29	7:30	2:00	6.5
167	240	lite brown weathered BR. (soft)	Develop	"	2:00	5:00	3
			Tripout - replace O-rings on Air box inlet set compressor clutch Crew travel	"	5:00	7:00	2
			crew travel move off. 0.5 GPM up to 230'	Aug 30	6:00	8:00	2

Rcrod. of Casing & Pipe

Size	Type	Size	Type
6			
Feet	Inch	Feet	Inch
177	6		

Remarks:

1- shoe.
3 GPM

Static Level	Total Rig Time	hrs.
Ground Level 86	Total Standby	hrs.
Top Of Casing	Drilling Mud	sacks

SIGNATURES

MIDNIGHT SUN.....
TITLE.....

CLIENT... J. Demianenko...
TITLE.....