


105 D 08

FIELD REPORT

204080034



Midnight Sun Drilling Co. Ltd.
#13 MacDonald Road
WHITEHORSE, Y.T. Y1A 4L1
Phone (403) 633-3070

Started Aug. 4.....1997

Completed Aug. 6.....1997

539795 ± 30 / 100m 204080034
6704770

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
MARY Redloch 97-8-15	W/W	LOT 776 OLD CONSTABULARY BUNCH

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE				
			move on set up	Aug 4	10:30	12:00	1.5
0	32	fill		"	12:00	6:30	6.5
32	47	silt Br sand.					
47	100	BR.	crew travel.	"	6:30	7:30	1
			crew travel	Aug 5	8:00	9:00	1
100	160	BR.		"	9:00	11:00	2
			crew travel	Aug 6	8:00	9:00	1
			move off.	"	9:00	12:00	3
			crew travel	"	12:00	1:00	1

Rcd. of Casing & Pipe				Remarks: 30 GPM 1-drive shoe
Size	Type	Size	Type	
6				
Feet	Inch	Feet	Inch	
60				

STATIC LEVEL	Total Rig Time	hrs.
Ground level 29'	Total Standby	hrs.
Top of casing	Drilling Mud	sacks

SIGNATURES

MIDNIGHT SUN. Inc.
TITLE Chris Braden

CLIENT.....
TITLE.....