

204080036

105 D 08



Field Report

13 MacDONALD ROAD
WHITEHORSE, YUKON
Y1A 4L1

540458;
6703895 ± 30/100m

Started..Sept. 2.....1982

Completed..Sept. 3.....1982

PHONE (403) 633-3070
TELEX 036-8496

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
Chris Erler	W/W	Lot # 28
	88-1A-32	New Constakology subd.

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE				
			Loading	Sept 2	8:00	3:00	7
			move on set up	"	4:00	5:30	1.5
0	32	silt	Gr cobs.				
32	40	Till	Cobs. silt Gr. layers.				
40	131	Till	cobs. silt Gr. layers	Sept 3	7:00	5:30	10.5
131	176	clay					
176	190	Till	cobs. silt Gr. layers				
190	215	soft	weathered BR.				
			Develop	"	5:30	7:30	2
			move off to shop	"	7:30	9:00	1.5

Rcd. of Casing & Pipe

Size	Type	Size	Type
Feet	Inch	Feet	Inch
195			
20'	B.R		
	Wen		

Remarks:

1 - shoe
1.5 GPM. X

Static Level	Total Rig Time	hrs.
Ground Level	Total Standby	hrs.
Top Of Casing	Drilling Mud	sacks

SIGNATURES

MIDNIGHT SUN.....
TITLE.....

CLIENT.....
TITLE.....