

204110289



Field Report

PH. 633-3070 TELEX 036-8496
P.O. BOX 4391
WHITEHORSE, YUKON

204110289
105 D 11 - 0289
496674
672 7574 ± 3100/300m

Started... July 8... 1991

Completed... July 16... 1991

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
	W / W set 4 1/2" liner	H.I. country R.V. Park 91-1-17

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE				
			move on set up	July 8	8:00	1:00	5
			Pull back 10' of casing				
90	130	cased	Leadrig	"	1:00	6:30	5.5
130	200	cased	Trip out	July 9	8:00	5:30	9.5
			Leadrig	"	6:30	7:30	1
			Trip out	"	5:30	6:30	1
			Leadrig	"	6:30	7:00	0.5
			Leadrig	July 10	8:00	9:30	1.5
			Trip in 5 1/2" DHA. bit	"	9:30	5:00	7.5
200	250	reamed	d. casing				
			Trip Hole	July 11	8:00	5:30	9.5
200	227	cased	shoe broke				
227	245	reamed	with edex bit				
			Leadrig	"	5:30	6:30	1
245	400	reamed	with 5 1/2" tricone	July 12	8:00	5:00	9
			Load trip out	July 13	8:00	11:00	3
			set 285' liner	"	11:00	4:00	5
			Pull 16' of 6" casing	"	4:00	6:00	2.

Ord. of Casing & Pipe				Remarks:
Size	Type	Size	Type	
Feet	Inch	Feet	Inch	

Static Level	Total Rig Time	hrs.
Ground Level	Total Standby	hrs.
Top Of Casing	Drilling Mud	sacks

SIGNATURES

MIDNIGHT SUN.....
TITLE.....

CLIENT.....
TITLE.....

