204110299

Field Report

MIDNIGHT SUN DRILLING CO. LTD. WHITEHORSE Y.T.

13 MacDONALD ROAD
WHITEHORSE, YUKON
Y1A 4L1

PHONE (403) 633-3070
TELEX 036-8496

105D11

497 0813
672 6623 ± 100/300m

Started July 28 1991

Completed July 31 1991

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
	W/W	Paddle Wheel
	94-17.16	

FORMATION LOG FROM	TO	FORMATION	DESCRIPTION OF WORK	TIME DATE	FROM	TO	HOURS
			MOVE				
			Load	July 28	9:00	12:00	3
			move on set up	"	12:30	2:30	2
0	26	Gr.	sand	"	2:30	6:00	3.5
26	58	Gr.	sand silt cobs				
58	60	Till					
60	126	Till		July 29	8:00	7:00	11
126	141	silt	Clay				
141	166	Till					
166	200	Hard	silt Clay odd cob.				
200	306	Hard	silt Clay odd cob.	July 30	8:00	6:00	10
306	312	runny	silt				
312	313	BR					
			Trip hole, Broke sandline chain	July 31	9:00	12:00	3
313	317	Broken	BR	~~"~~	~~12:00~~		
			Develop	"	12:00	4:00	4
			Trip out	"	4:00	5:00	1

crd. of Casing & Pipe Size	Type	Size	Type
6			
Feet	Inch	Feet	Inch
314	6		

Remarks: 60 GPM
1-drive shoe

Static Level		Total Rig Time	hrs.
Ground Level	35'	Total Standby	hrs.
Top Of Casing		Drilling Mud	sacks

SIGNATURES

MIDNIGHT SUN..... CLIENT.....

TITLE..... TITLE.....

Willow Printers