



Field Report B-10 204140144

13 MacDONALD ROAD
WHITEHORSE, YUKON
Y1A 4L1

Started July 11.....1988

PHONE (403) 633-3070
TELEX 036-8496

Completed July 17.....1988

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
Mary Regan (REGAN) Box 4521, Whitehorse Yukon Y1A 2R8 633-5424	W/W 88-1A-26	Lot #13 Pilot Mountain

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE				
			Load, in	July 11	1:00	3:30	2.5
			move on set up	"	3:30	4:30	1
0	3	sand Br	7 7/8" to 15'	"	4:30	7:00	2.5
3	15	BR					
			set 17' - 6" casing and cemented				
15	155	BR	1- GPM 112'	July 12	7:00	4:00	9
			Rig motor repair	"	4:00	6:30	2.5
155	240	BR		July 15	8:00	7:30	11.5
240	303	BR		July 16	7:00	1:00	6
			Develop	"	1:00	3:00	2
			Trip out	"	3:00	4:00	1
			move off	July 17	8:00	10:00	2

Rcord. of Casing & Pipe

Size	Type	Size	Type
6		8	
Feet	Inch	Feet	Inch
17		4'	

Remarks:

1- 6" shoe
1- bag cement - redimix
2 Co. P.M.

Static Level	Total Rig Time	hrs.
Ground Level <u>59'</u>	Total Standby	hrs.
Top Of Casing	Drilling Mud	sacks

SIGNATURES

MIDNIGHT SUN.....

CLIENT Mary Regan.....

TITLE.....

TITLE.....