B·ID 204140154

Field Report

MIDNIGHT SUN DRILLING CO. LTD. WHITEHORSE Y.T.

PH. 633-3070 TELEX 036-8496
P.O. BOX 4391
WHITEHORSE, YUKON

Started Sept. 23 198

Completed ..... 19..

(2)

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
Doug Smith	W/W	Hot springs Ro
	88-1A-39	

FORMATION LOG FROM	TO	FORMATION	DESCRIPTION OF WORK	TIME DATE	FROM	TO	HOURS
			MOVE				
			move 4' set up	sept. 27	5:00	7:00	2
0	160	silt	Broke inner tube	sept 28	8:00	4:00	8
			took hammer to shop	"			
			mounted hammer unable	sept. 29	8:30	7:00	10.5
			to get hammer working				
160	200	silt		"	7:00	8:30	1.5
			broke bottom 20' weld.				
			Trip out pull	sept 30	8:00	10:00	2
			180' casing				

Rcrd. of Casing & Pipe Size	Type	Size	Type
Feet	Inch	Feet	Inch

Remarks: Lost
30' casing
1 - shoe.

Static Level	Total Rig Time hrs.
Ground Level	Total Standby hrs.
Top Of Casing	Drilling Mud sacks

SIGNATURES

MIDNIGHT SUN ....h.e.s.....

TITLE .....Travis.....

Carl - 21 hrs

CLIENT .....

TITLE .....

Willow Printers