



# Field Report

14

13 MacDONALD ROAD  
WHITEHORSE, YUKON  
Y1A 4L1  
PHONE (403) 633-3070  
TELEX 036-8496

204140162

Started Sept 23 1992  
Completed Sept 24 1992

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
Bill G. BARR Whitehorse Alaska Highway	WATER Well	near 2nd Mile Alaska Highway

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
0	20	Silt	MOVE Loading	Sept 23	8:00	8:45	:45
20	23	till	Loading, haul - Set up	Sept 23	8:45	12:30	2:45
23	285	B.R.	move on set Phil 0-165	Sept 23	12:30	12:30	28:54
0	16	silt	Phil - 165-285	Sept 24	12:30	6:30	57.5
16	36	clay	Wash - Develop	Sept 24	3:30	4:30	1
36	37	clay	Bill - Move on R	Sept 24	4:30	5:15	4.5
37	90	B.R.	thru - Show	Sept 24	5:15	5:30	:15
90	310	B.R.		Sept 9	8:00	5:30	9.5
			Loading	"	5:30	6:00	0.5
310	490	HR BR	Casing - 5/8"	Sept 10	8:00	6:30	10.5
490	502	B.R.	Loading	Sept 11	8:00	10:00	2
				"	12:00	12:00	2
			Broke 2 7/8" Pin on top of XL-5 hammer Fish for hammer	"	12:00	6:30	6.5

Recd. of Casing & Pipe			
Size	Type	Size	Type
6	200	6	200
Feet	Inch	Feet	Inch
246			

Remarks: - approx - 1/2 G.P.M.  
5/8"  $\phi$  Hole in BEDROCK  
11 6 3/4" Drive Show

Static Level	Total Rig Time	19:15 hrs.
Ground Level	Total Standby	hrs.
Top of Casing	Drilling Mud	sacks

SIGNATURES

MIDNIGHT SUN.....  
TITLE.....

CLIENT.....  
TITLE.....