MIDNIGHT SUN DRILLING CO. LTD.
PH: 668-2434
WHITEHORSE Y.T.
P.O. Box 4391

FIELD REPORT

204140172

Started May 22 1974
Completed May 23 1974

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
Merv. Tull	Water Well	930 Alaska Hwy.

FORMATION LOG FROM	TO	FORMATION
0	7'6"	Sand & Gravel
7'6"	27'	Sand with silty sand layers
27'	34'	Sandy silty (wet)
34'	40	Clayey silt
40	46'	Gravelly clay
46'	47'	Broken rock

DESCRIPTION OF WORK

MOVE Water Well
Move off

Bottom open
Perf. 28'-33'

TIME DATE	FROM	TO	HOURS
May 22/74	08.00	20.00	12 hrs
May 23/74	10.00	12:00	2 hrs

Rcrd. of Casing & Pipe Size	Type	Size	Type
5"			
Feet	Inch	Feet	Inch
44'			

Remarks:

STATIC LEVEL
Ground level 21'6"
Top of casing 22'6"

Total Rig Time 14.0 hrs.
Total Standby hrs.
Drilling Mud 3 sacks

SIGNATURES

DNIGHT SUN.....
'LE.....

CLIENT.....
TITLE.....