Field Report

204140177

Started..April 27.....19.89

Completed.....19....

MIDNIGHT SUN DRILLING CO. LTD.
WHITEHORSE Y.T.
PH. 633-3070 TELEX 036-8496
P.O. BOX 4391
WHITEHORSE, YUKON

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
Brian Cox	Water Well	Yukon River (Behind Legal Branches)

FORMATION LOG FROM	TO	FORMATION
0	21'	Sand
21	63'	Silt
63'	210	Clay
208'	215	Gravel
215 -	220	Sand

DESCRIPTION OF WORK
MOVE Load.
travel to Site
Unload. walk to Hole #1
Drill test hole 0-50'
Change to 6" x Move
Drill 0-40'
Load - Shop
travel
Drill 40-162'
travel
Load.
travel
Pull Rods check Hammer
Return to Shop For 6" x Bits
Drill 162' - 220'
trip to Set Screen
travel

TIME DATE	FROM	TO	HOURS
27	8:30	9:00	
	9:00	9:30	
	9:30	10:00	
	10:00	11:00	
	11:00	12:00	
	12:00	1:30	
29	8:00	8:30	
	9:30	9:00	
	9:00	7:00	
	7:00	7:30	
30	8:00	8:30	
	8:30	9:00	
	9:00	10:00	
	10:00	12:00	
	12:00	16:00	
	16:00	20:00	
	20:00	20:30	

Rcrd. of Casing & Pipe Size	Type	Size	Type
Feet	Inch	Feet	Inch

Remarks: Lost - 1 new Reamer Bit, 1 Used Pilot.
Used 222' Casing.
Lost 2 Screens - 2 K Packers
2 Bottoms - 1 Riser Pipe.
1 6" x Casing Shoe

Static Level		Total Rig Time	hrs.
Ground Level		Total Standby	hrs.
Top Of Casing		Drilling Mud	sacks

SIGNATURES

MIDNIGHT SUN.....

TITLE.....

CLIENT.....

TITLE.....

Willow Printers