Field Report

204140181

Started MAY 9 19 81

Completed ..... 19....

MIDNIGHT SUN DRILLING CO. LTD.
WHITEHORSE Y.T.
PH. 633-3070
P.O. BOX 4391
WHITEHORSE, YUKON

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
DAVE JAMIESON	W/W	MAYO Rd

FORMATION LOG FROM	TO	FORMATION	DESCRIPTION OF WORK	TIME DATE	FROM	TO	HOURS
			MOVE TRAVEL To site	9	1:15	1:30	
			Moved on set up	9	1:30	2:30	
					2:30	6:00	
0'	26'	Fine silty	sand				
26'	29'	Fine	SAND				
29'	60'	Fine silty	sand				
60'	62'	Blue Clay					
62'	73'	Till	(Blue clay gravel + sand)				
73'	85	Bedrock					
			Flush Hole Pullout Load	9.	6:00	6:~~45~~	
			TRAVEL To SHOP	11	6:~~45~~	7:00	

Rcrd. of Casing & Pipe Size	Type	Size	Type
Feet	Inch	Feet	Inch

Remarks:

Static Level		Total Rig Time	hrs.
Ground Level		Total Standby	hrs.
Top Of Casing		Drilling Mud	sacks

SIGNATURES

MIDNIGHT SUN..... CLIENT.....

TITLE..... TITLE.....

Willow Printers