



Field Report

204140194

13 MacDONALD ROAD
WHITEHORSE, YUKON
Y1A 4L1

Started June 4.....1992

Completed June 5.....1992

PHONE (403) 633-3070
TELEX 036-8496

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
Ruth MacLaugh	W/W	5 mile Rd
	92-1A-14	

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE				
			move on set up.	June 4	8:00	10:00	2
0	17	silt	some Gr.	"	10:00	6:00	8
17	72	clay	silt				
72	77	silt	sand Gr.				
77	79	clay	Gr.				
79	84	silt	Gr. sand				
84	160	silt					
160	197	silt		June 5	8:00	1:00	5
197	211	silt	clay some Gr.				
211	230	silt					
230	241	fine	sand Gr. silt	"	7:00	2:00	1
			set screen	"	2:00	4:30	2.
			Develop	"	4:30	5:30	1
			move off to shop				

Rcrod. of Casing & Pipe

Size	Type	Size	Type
Feet	Inch	Feet	Inch
6.			
240			

Remarks:

1- ody shoe

20 slot screen

K packer 2' riser

5/8 bit pin

5 B pm

Static Level	Total Rig Time	hrs.
Ground Level 134' + rising	Total Standby	hrs.
Top Of Casing	Drilling Mud	sacks

SIGNATURES

MIDNIGHT SUN.....
TITLE.....

CLIENT.....
TITLE.....