

DRILLER PAUL LUNDGREN

DATE AUG 3<sup>RD</sup> 2005

OVERBURDEN TYPE

LOT # 1223  
PLAN 91-26 HOT SPRINGS ROAD.

FROM	TO	
<u>0</u>	<u>12</u>	<u>SAND CLAY ROCKS</u>
<u>12</u>	<u>33</u>	<u>BROKEN CRUSHED ROCK.</u>
<u>33</u>	<u>205</u>	<u>BED ROCK.</u>

BEDROCK

ELEVATION 2320 G.P.S. READING  
N 60° 52.570 UNCORRECTED  
135° 21.158

FROM 33 TO 205

10 INCH GROUT SEAL WITH BENTONITE CHIPS

TOTAL HOLE DEPTH ----- FEET 205

STEEL CASING DEPTH ----- FEET 45 SIZE 6 INCH

P.V.C. CASING DEPTH ----- FEET \_\_\_\_\_ SIZE \_\_\_\_\_ INCH

TOP OF SCREEN ----- FEET \_\_\_\_\_

DEPTH OF AQUIFER ----- FEET 191

STANDING WATER LEVEL ----- FEET 91

APPROXIMATE FLOW RATE ---- G.P.M. 6 TO 7

COMMENTS:

BED ROCK BADLY BROKEN - HAD TO RUN  
CASING TO 45 FT. - PRESSURE SYSTEM INSTALLED  
WATER SAMPLES TAKEN - WELL DISINFECTED.