

204140359

Field Report

105D14

Started... APR... 28... 1988

489 764 ±1000/3000m
6744596

Completed... MAY... 2... 1988



PH. 633-3070 TELEX 036-8496
P.O. BOX 4391
WHITEHORSE, YUKON

88-1A-10

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
Risk Bonyester W/W		2 mile Maya Rd. Lot 26 / Just Before Baider

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE				
			loading	APR 28	11:00	3:00	4
			move on set up	"	3:00	3:30	0.5
					3:30	6:00	2.5
0	12	sand.					
12	17	Gr. sand					
17	60	Clay silt					
60	159	clay silt		APR 29	8:00	4:00	8
159	164	Gr. sand silt					
			Brake Hyd Hose				
164	176	Gr. sand same silt		MAY 1	8:00	11:00	3
			Develop	"	1:00	3:00	2
			move off to shop	"	3:00	4:00	1

Rcrd. of Casing & Pipe			
Size	Type	Size	Type

Remarks:

1 - shoe.
2' riser lead packer
15 slot
5 3/8" bit pin
50 GPM

Static Level	Total Rig Time	hrs.
Ground Level 16'	Total Standby	hrs.
Top Of Casing	Drilling Mud	sacks

SIGNATURES

MIDNIGHT SUN... *Les. T.*
TITLE... *Geoff. C.*

CLIENT.....
TITLE.....