204140371

Field Report

105D14

490370
6757927;
zone 8N ± 1000/3000 m

Started Nov 20 19 92

Completed Nov 20 19 92

MIDNIGHT SUN DRILLING CO. LTD.
WHITEHORSE Y.T.
PH. 633-3070 TELEX 036-8496
P.O. BOX 4391
WHITEHORSE, YUKON

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
		Mile 7 Mayo Road
Acorn Sawmill	Cleanout Water Well.	
	rig 1	

FORMATION LOG FROM	TO	FORMATION	DESCRIPTION OF WORK	TIME DATE	FROM	TO	HOURS
			MOVE				
			Move on Set up.				
			+ Trip in to Bottom.				
			Pump Water Down hole.				
			to Clean out				
					total time		
			Travel Back to Shop.		5 hours.		
			5 HRS. @ 220/HR.				

Rcrd. of Casing & Pipe Size	Type	Size	Type
Feet	Inch	Feet	Inch

Remarks:

Static Level was at 15' + Rising

5" casing

Static Level 15' +	Total Rig Time 5 hrs.
Ground Level	Total Standby hrs.
Top Of Casing	Drilling Mud sacks

SIGNATURES

MIDNIGHT SUN Trent

TITLE

CLIENT

TITLE

Willow Printers