



PH. 633-3070  
P.O. BOX 4391  
WHITEHORSE, YUKON

# Field Report

no lot @ mile  
1.5 mayo road.

105D14

#204140375

Started May 10.....1985

Completed May 13.....1985

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
Bill Ryan behind Browns in trailer	W/U	Mayo Rd. mile 1.5

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE				
			move set up	May 10	2:00	3:00	1
0'	5'	sand		"	3:00	7:00	4
5'	8'	sand Gr.					
8'	80'	clay silt	loading	May 11	8:00	9:00	1
80'	105'	clay silt		"	9:00	2:00	5
105'	124'	clay silt Gr.					
124'	126'	Gr.					
126'	188'	silt	set screen	"	2:00	6:00	4
			set screen Developer	May 13	8:00	3:00	7
			Pull screen				
128'	133'	silt some Gr.		"	3:00	4:00	1
133'	136'	Gr. sand	set screen Developer	"	4:00	7:00	3

Rcprd. of Casing & Pipe

Size	Type	Size	Type
6			
Feet	Inch	Feet	Inch
136			

Remarks:

1 - drive shoe.  
1 - 25 slot screen head packer  
1 - 2' riser  
1 - 5/8" bit pin

Static Level	Total Rig Time	hrs.
Ground Level	Total Standby	hrs.
Top Of Casing	Drilling Mud	sacks

SIGNATURES

MIDNIGHT SUN.....

TITLE.....

CLIENT.....

TITLE.....