



# Field Report

211030017

Started Apr. 26.....1990

Completed Apr. 29...1990

PH. 633-3070 TELEX 036-8496  
P.O. BOX 4391  
WHITEHORSE, YUKON

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
Harold Boehm	W / W	Tintina sub Div. Far Lot #10
	90-1A-8	

FORMATION LOG			DESCRIPTION OF WORK	TIME			
FROM	TO	FORMATION		DATE	FROM	TO	HOURS
			MOVE				
			move on set up	Apr. 26	7:30	9:30	2
0	3	silt	Gr.	"	9:30	11:00	1.5
3'	20'	till					
20	70	till	Broke casing last 24' plus shoe moved 5'	Apr 27	7:00	9:30	14.5
0	3'	silt Gr.					
3	80'	till	Broke shoe from casing pulled casing replaced oring in Hyd. Bank				
0'	3'	silt Gr.		Apr. 28	7:00	6:00	11
3'	173	till					
173	225	BR					
			move off Drill stuck Flat Deck still stuck	"	6:00	10:00	4
			Pull 51 out loading	APR 29	8:30	11:00	2.5
			Travel to Wheel.	"	11:00	4:30	1.5

Rcrd. of Casing & Pipe				Remarks:
Size	Type	Size	Type	
6 5/8				Last 24' casing Plus shoe.
Feet	Inch	Feet	Inch	
178				3-odox shoe.
				No water
				Static Level
				Ground Level
				Top Of Casing
				Total Rig Time hrs.
				Total Standby hrs.
				Drilling Mud sacks

SIGNATURES

MIDNIGHT SUN..... Les Jorgenson (Driller)  
TITLE..... Les Shaw (Helper)

CLIENT..... H. Boehm  
TITLE.....